Leica 3D Disto

User Manual



Version 4.0 **English**

- when it has to be **right**





Introduction

Purchase

Congratulations on the purchase of the Leica 3D Disto.





This manual contains important safety directions as well as instructions for setting up the product and operating it. Refer to "1 Safety Directions" for further information. Read carefully through the User Manual before you switch on the product.

Product Identification

The type and serial number of your product are indicated on the type plate. Always refer to this information when you need to contact your agency or Leica Geosystems authorised service workshop.

Trademarks

• Windows is a registered trademark of Microsoft Corporation in the United States and other countries

All other trademarks are the property of their respective owners.

Available Documentation

Name	Description/Format		Afeba
3D Disto Quick Start	Intended as quick reference field guide.	✓	✓
3D Disto User Manual	All instructions required in order to operate the instrument at a basic level are contained in this User Manual. Provides an overview of the instrument together with technical data and safety directions.	-	✓
Safety Manual	Provides important safety instructions for use of 3D Disto.	✓	✓

Refer to the following resources for all 3D Disto documentation/software:

- Leica USB memory stick
- https://myworld.leica-geosystems.com



myWorld@Leica Geosystems (https://myworld.leica-geosystems.com) offers a wide range of services, information and training material.

With direct access to myWorld, you are able to access all relevant services whenever it is convenient for you, 24 hours a day, 7 days per week. This increases your efficiency and keeps you and your equipment instantly updated with the latest information from Leica Geosystems.

Service	Description
myProducts	Add all Leica Geosystems products that you and your company own. View detailed information on your products, buy additional options or Customer Care Packages (CCPs), update your products with the latest software and keep up-to-date with the latest documentation.
myService	View the service history of your products in Leica Geosystems Service Centres and detailed information on the services performed on your products. For your products that are currently in Leica Geosystems Service Centres view the current service status and the expected end date of service.
mySupport	Create new support requests for your products that will be answered by your local Leica Geosystems Support Team. View the complete history of your Support and view detailed information on each request in case you want to refer to previous support requests.
myTraining	Enhance your product knowledge with the Leica Geosystems Campus - Information, Knowledge, Training. Study the latest online training material or download training material on your products. Keep up-to-date with the latest News on your products and register for Seminars or Courses in your country.
myTrustedServices	Offers increased productivity while at the same time providing maximum security. • myExchange With myExchange you can exchange any files/objects from your computer to any of your Leica Exchange Contacts. • mySecurity If your instrument is ever stolen, a locking mechanism is available to ensure that the instrument is disabled and can no longer be used.

Table of Contents

this manual	Cha	pter		Page
	1	Safet	y Directions	6
		1.1	General Introduction	6
		1.2	Definition of Use	7
		1.3	Limits of Use	7
		1.4	Responsibilities	7 8
		1.5	Hazards of Use	
		1.6	Laser Classification	9
			1.6.1 General	9
			1.6.2 Integrated Distance Meter	10
		1.7	Electromagnetic Compatibility EMC	11
		1.8	FCC Statement, Applicable in U.S.	12
		1.9	Déclaration FCC, propre aux Etats-Unis	13
	2		ription of the System	15
		2.1	Overview	15
		2.2	Container Contents	15
		2.3	Instrument Components	16
			2.3.1 3D Disto	16
		٦./	2.3.2 RM100 Remote Control	18
		2.4	Power Supply	18
		2.5	3D Disto Software	20
			2.5.1 Software Concept2.5.2 User Interface	20 21
	-	l t		
	3		ument Setup	25
		3.1	Setting Up 3D Disto	25
		3.2	Connecting the 3D Disto to a Windows Device Assistant	25
		3.3	Tilt Sensor	26
		3.4		27
		3.5 3.6	Device Configuration and Menu Settings	27 29
		3.0	Data Management 3.6.1 File Manager	29
			3.6.2 Export and Import of Data	30
		3.7	Calculator	31
	4		nical Terms and Abbreviations	32
	5	Opera	ation	
		5.1	Measurements	35
		5.2	Pointfinder	35
		5.3	Measurement Workflow	36
	6	Softw	vare Applications	40
		6.1	Overview	40
		6.2	Measure	40
			6.2.1 Reference Height	40
			6.2.2 Scan Tool for Automated Scans	41
			6.2.3 CAD Tools	44
		6.3	Projector	51
			6.3.1 Workflow	51
			6.3.2 Targeting and Layout with RM100 Remote Control	54
		6.4	Location	55

	6.5	Tool Kit		57
		6.5.1	Comfort Plumbing	57
		6.5.2	Comfort Targeting	58
		6.5.3	Comfort Level	59
		6.5.4	Meter Mark	59
		6.5.5	Height Tracking	60
		6.5.6	Parallel Line	61
7	Error	Messages		62
8	Check	& Adjust		63
	8.1	Overvie	W	63
	8.2	Tilt Sens	sor Calibration	63
	8.3	Crossha	irs Offset	64
	8.4	V-Index	Error	64
	8.5	Reset to	Factory Settings	65
9	Instru	ment Prot	tection (Theft Protection)	66
10	Care a	ınd Transp	port	67
	10.1	Transpo	rt	67
	10.2	Storage		67
	10.3	Cleaning	g and Drying	68
11	Techn	ical Data		69
	11.1	Technica	al Data	69
	11.2	Conform	nity to National Regulations	70
	11.3	Dangero	ous Goods Regulations	71

1

1.1

Safety Directions

General Introduction

Description

The following directions enable the person responsible for the product, and the person who actually uses the equipment, to anticipate and avoid operational hazards.

The person responsible for the product must ensure that all users understand these directions and adhere to them.

About Warning Messages

Warning messages are an essential part of the safety concept of the instrument. They appear wherever hazards or hazardous situations can occur.

Warning messages...

- make the user alert about direct and indirect hazards concerning the use of the product.
- contain general rules of behaviour.

For the users' safety, all safety instructions and safety messages shall be strictly observed and followed! Therefore, the manual must always be available to all persons performing any tasks described herein.

DANGER, WARNING, CAUTION and NOTICE are standardized signal words for identifying levels of hazards and risks related to personal injury and property damage. For your safety it is important to read and fully understand the table below with the different signal words and their definitions! Supplementary safety information symbols may be placed within a warning message as well as supplementary text.

Туре	Description
M DANGER	Indicates an imminently hazardous situation which, if not avoided, will result in death or serious injury.
MARNING	Indicates a potentially hazardous situation or an unintended use which, if not avoided, could result in death or serious injury.
A CAUTION	Indicates a potentially hazardous situation or an unintended use which, if not avoided, may result in minor or moderate injury.
NOTICE	Indicates a potentially hazardous situation or an unintended use which, if not avoided, may result in appreciable material, financial and environmental damage.
	Important paragraphs which must be adhered to in practice as they enable the product to be used in a technically correct and efficient manner.

1.2 **Definition of Use**

Intended Use

- 3D measuring of distances, heights, grades, angles, area and volume.
- Manual and automatic measurement of room dimensions.
- Automatic measurement of profiles.
- Laying out points and designs, for example from blueprint.
- Generation of drawings.
- Camera functionality.
- Import/Export of data.
- Administration of data.

Reasonably foreseeable misuse

- Use of the product without instruction.
- Use outside of the intended use and limits.
- Disabling safety systems.
- Removal of hazard notices.
- Opening the product using tools, for example screwdriver, unless this is permitted for certain functions.
- Modification or conversion of the product.
- Use after misappropriation.
- Use of products with obvious damages or defects.
- Use with accessories from other manufacturers without the prior explicit approval of Leica Geosystems.
- Inadequate safeguards at the working site.
- Deliberate dazzling of third parties.
- Controlling of machines, moving objects or similar monitoring application without additional control and safety installations.

1.3 Limits of Use

Environment

Suitable for use in an atmosphere appropriate for permanent human habitation: not suitable for use in aggressive or explosive environments.



DANGER

Local safety authorities and safety experts must be contacted before working in hazardous areas, or close to electrical installations or similar situations by the person in charge of the product.

1.4

Responsibilities

Manufacturer of the product

Leica Geosystems AG, CH-9435 Heerbrugg, hereinafter referred to as Leica Geosystems, is responsible for supplying the product, including the user manual and original accessories, in a safe condition.

Person responsible for the product

The person responsible for the product has the following duties:

- To understand the safety instructions on the product and the instructions in the user manual.
- To ensure that it is used in accordance with the instructions.
- To be familiar with local regulations relating to safety and accident prevention.
- To inform Leica Geosystems immediately if the product and the application becomes unsafe.
- To ensure that the national laws, regulations and conditions for the operation of e.g. radio transmitters or lasers are respected.



1.5

Hazards of Use



CAUTION

Watch out for erroneous measurement results if the product has been dropped or has been misused, modified, stored for long periods or transported.

Precautions:

Periodically carry out test measurements, particularly after the product has been subjected to abnormal use and before and after important measurements.



WARNING

During dynamic applications, for example stakeout procedures there is a danger of accidents occurring if the user does not pay attention to the environmental conditions around, for example obstacles, excavations or traffic.

Precautions:

The person responsible for the product must make all users fully aware of the existing dangers.



WARNING

Inadequate securing of the working site can lead to dangerous situations, for example in traffic, on building sites and at industrial installations.

Precautions:

Always ensure that the working site is adequately secured. Adhere to the regulations governing safety, accident prevention and road traffic.



CAUTION

If the accessories used with the product are not properly secured and the product is subjected to mechanical shock, for example blows or falling, the product may be damaged or people can sustain injury.

Precautions:

When setting-up the product, make sure that the accessories are correctly adapted, fitted, secured, and locked in position.

Avoid subjecting the product to mechanical stress.



WARNING

During the transport, shipping or disposal of batteries it is possible for inappropriate mechanical influences to constitute a fire hazard.

Precautions:

Before shipping the product or disposing of it, discharge the batteries by running the product until they are flat.

When transporting or shipping batteries, the person in charge of the product must ensure that the applicable national and international rules and regulations are observed. Before transportation or shipping contact your local passenger or freight transport company.



WARNING

High mechanical stress, high ambient temperatures or immersion into fluids can cause leakage, fire or explosions of the batteries.

Precautions:

Protect the batteries from mechanical influences and high ambient temperatures. Do not drop or immerse batteries into fluids.



WARNING

If battery terminals are short circuited e.g. by coming in contact with jewellery, keys, metalized paper or other metals, the battery can overheat and cause injury or fire, for example by storing or transporting in pockets.

Precautions:

Make sure that the battery terminals do not come into contact with metallic objects.



If the product is improperly disposed of, the following can happen:

- If polymer parts are burnt, poisonous gases are produced which may impair health.
- If batteries are damaged or are heated strongly, they can explode and cause poisoning, burning, corrosion or environmental contamination.
- By disposing of the product irresponsibly you may enable unauthorised persons to use it in contravention of the regulations, exposing themselves and third parties to the risk of severe injury and rendering the environment liable to contamination.

Precautions:



The product must not be disposed with household waste.

Dispose of the product appropriately in accordance with the national regulations in force in your country.

Always prevent access to the product by unauthorised personnel.

Product-specific treatment and waste management information can be downloaded from the Leica Geosystems home page at http://www.leica-geosystems.com/treatment or received from your Leica Geosystems distributor.



Only Leica Geosystems authorised service workshops are entitled to repair these products.

1.6

Laser Classification

1.6.1

General

General

The following chapters provide instructions and training information about laser safety according to international standard IEC 60825-1 (2014-05) and technical report IEC TR 60825-14 (2004-02). The information enables the person responsible for the product and the person who actually uses the equipment, to anticipate and avoid operational hazards.



According to IEC TR 60825-14 (2004-02), products classified as laser class 1, class 2 and class 3R do not require:

- laser safety officer involvement,
 - protective clothes and eyewear,
 - special warning signs in the laser working area

if used and operated as defined in this User Manual due to the low eye hazard level.



National laws and local regulations could impose more stringent instructions for the safe use of lasers than IEC 60825-1 (2014-05) and IEC TR 60825-14 (2004-02).



Integrated Distance Meter

Integrated Distance Meter

The Leica 3D Disto produces a visible laser beam which emerges from the front of the instrument.

The laser product described in this section is classified as laser class 2 in accordance

• IEC 60825-1 (2014-05): "Safety of laser products"

These products are safe for momentary exposures but can be hazardous for deliberate staring into the beam. The beam may cause dazzle, flash-blindness and after-images, particularly under low ambient light conditions.


Description	Value
Wavelength	620 nm - 690 nm
Maximum average radiant power	<1 mW
Pulse repetition frequency	320 MHz
Pulse duration	<1 ns
Beam divergence	0.16 mrad x 0.6 mrad



From a safety perspective, class 2 laser products are not inherently safe for the eyes. **Precautions:**

- 1) Avoid staring into the beam or viewing it through optical instruments.
- 2) Avoid pointing the beam at other people or at animals.

Labelling



a) Laser beam

Laser Radiation Do not stare into the beam Class 2 Laser Product according to IEC 60825-(2014 - 05) $Po \leq 1.00 \text{ mW}$ $\lambda = 620 - 690 \text{ nm}$

Electromagnetic Compatibility EMC

Description

The term Electromagnetic Compatibility is taken to mean the capability of the product to function smoothly in an environment where electromagnetic radiation and electrostatic discharges are present, and without causing electromagnetic disturbances to other equipment.



WARNING

Electromagnetic radiation can cause disturbances in other equipment.

Although the product meets the strict regulations and standards which are in force in this respect, Leica Geosystems cannot completely exclude the possibility that other equipment may be disturbed.

The product is a class A product when operated with the internal batteries. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.



CAUTION

There is a risk that disturbances may be caused in other equipment if the product is used with accessories from other manufacturers, for example field computers, personal computers or other electronic equipment, non-standard cables or external batteries.

Precautions:

Use only the equipment and accessories recommended by Leica Geosystems. When combined with the product, they meet the strict requirements stipulated by the guidelines and standards. When using computers or other electronic equipment, pay attention to the information about electromagnetic compatibility provided by the manufacturer.



CAUTION

Disturbances caused by electromagnetic radiation can result in erroneous measurements.

Although the product meets the strict regulations and standards which are in force in this respect, Leica Geosystems cannot completely exclude the possibility that the product may be disturbed by intense electromagnetic radiation, for example, near radio transmitters, two-way radios or diesel generators.

Precautions:

Check the plausibility of results obtained under these conditions.



If the product is operated with connecting cables attached at only one of their two ends, for example external supply cables, interface cables, the permitted level of electromagnetic radiation may be exceeded and the correct functioning of other products may be impaired.

Precautions:

While the product is in use, connecting cables, for example product to external battery, product to computer, must be connected at both ends.

Radios or Digital **Cellular Phones WARNING**

Use of product with radio or digital cellular phone devices:

Electromagnetic fields can cause disturbances in other equipment, in installations, in medical devices, for example pacemakers or hearing aids and in aircraft. It can also affect humans and animals.

Precautions:

Although the product meets the strict regulations and standards which are in force in this respect, Leica Geosystems cannot completely exclude the possibility that other equipment can be disturbed or that humans or animals can be affected.

- Do not operate the product with radio or digital cellular phone devices in the vicinity of filling stations or chemical installations, or in other areas where an explosion hazard exists.
- Do not operate the product with radio or digital cellular phone devices near to medical equipment.
- Do not operate the product with radio or digital cellular phone devices in aircraft.

1.8

FCC Statement, Applicable in U.S.



WARNING

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules.

These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and the receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.



This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

- 1) This device may not cause harmful interference, and
- 2) This device must accept any interference received, including interference that may cause undesired operation.



Changes or modifications not expressly approved by Leica Geosystems for compliance could void the user's authority to operate the equipment.



This device complies with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions:


- 1) This device may not cause harmful interference, and
- 2) This device must accept any interference, including interference that may cause undesired operation of the device.

SAR Information

FCC Radiation Exposure Statement

The radiated output power of the instrument is far below the FCC radio frequency exposure limits. Nevertheless, the instrument should be used in such a manner that the potential for human contact during normal operation is minimised. To avoid the possibility of exceeding the FCC radio frequency exposure limits, keep a distance of at least 20 cm between you (or any other person in the vicinity) and theantenna that is built into the instrument.

Labelling 3D Disto



Labelling RM100 Remote Control



1.9

Déclaration FCC, propre aux Etats-Unis



WARNING

Cet équipement a été testé et a respecté les limites imparties à un appareil numérique de classe B, conformément au paragraphe 15 des Règles FCC.

Ces limites sont prévues pour assurer une protection suffisante contre les perturbations dans une installation fixe.

Cet équipement génère, utilise et est en mesure de rayonner de l'énergie haute fréquence ; s'il n'est pas installé et utilisé conformément aux instructions, il peut causer des perturbations sérieuses aux communications radios. Il n'existe cependant aucune garantie que des interférences ne se produiront pas dans une installation particulière.

Si cet équipement devait gravement perturber la réception des émissions de radio et de télévision, ce qui peut être établi en mettant l'équipement sous puis hors tension, nous conseillons à l'utilisateur de tenter de remédier aux interférences en appliquant une ou plusieurs des mesures suivantes :

- réorienter l'antenne réceptrice ou la changer de place.
- augmenter la distance entre l'équipement et le récepteur
- connecter l'équipement à une sortie sur un circuit différent de celui sur lequel le récepteur est branché
- demander conseil à votre revendeur ou à un technicien radio/TV expérimenté.



Cet appareil est conforme à la section 15 des règlements FCC. Son fonctionnement est soumis aux deux conditions suivantes :

- 1) cet appareil ne doit pas causer d'interférences nuisibles, et
- 2) cet appareil doit accepter toute autre interférence reçue, y compris les interférences pouvant entraîner un fonctionnement non désiré.



Les modifications dont la conformité n'a pas expressément été approuvée par Leica Geosystems peuvent faire perdre à leur auteur son droit à utiliser l'équipement.

Ce dispositif est conforme à la norme RSS-210 d'Industrie Canada. L'utilisation est sujette aux deux conditions suivantes:


- ce dispositif ne pas doit pas être la source d'interférences nuisibles, et
- ce dispositif doit accepter toutes les interférences, y compris les interférences pouvant induire des opérations non souhaitées.

2 **Description of the System**

2.1 Overview

3D Disto General Description


The Leica 3D Disto is a three-dimensional measuring and projection system. To operate the 3D Disto you need a Windows® device. To perform certain functions you can also use the RM100 Remote Control.



- a) 3D Disto
- b) USB Cable
- c) Windows® device (not part of the delivery)
- d) RM100 Remote Control


2.2 **Container Contents**

Container Contents (1/2)



- a) 3D Disto with built-in SD WLAN card
- b) USB connection cable 3D Disto to the Windows® device
- c) Safety Instructions Manual, 3D Disto Quick Start, CE and Producer Certificate, USB memory stick (with licence keys, User Manual, Windows® software and setup information), WLAN USB stick
- d) Four country-specific cables for 3D Disto power supply
- e) Target marks, self-adhesive, 50 units in one bag
- f) RM100 remote control and battery

Container Contents (2/2)




- a) Ruler for offset points
- b) 3D Disto power supply

2.3 Instrument Components


2.3.1 3D Disto

Motor-driven Part



- a) LEDs for 3D Disto status
- b) ON/OFF button
- c) Grips to hold the instrument
- d) Infrared (IR) interface
- e) WLAN interface
- f) Laser distance meter with Pointfinder
- g) Circular bubble

Battery Socket



- a) Tripod thread 5/8"
- b) 90° marking
- c) Power supply connector for 3D Disto
- d) LED for battery status
- e) Data cable connector


LEDs and Buttons

Button/LEDs	Description
ON/OFF button	Button to turn instrument ON or OFF. Instrument turns OFF after 15 minutes if not connected to the PC.
LEDs for 3D Disto status	 Green and orange LEDs light up continuously: 3D Disto is booting. Orange LED flashes: Self-levelling procedure is running or tilt > 3°. Green LED flashes: 3D Disto is ready for measurement. Tilt sensor is on. Orange LED lights up continuously: An error occurred. Refer to "7 Error Messages". Green and orange LEDs light up continuously: Press the ON button to reset the instrument. For experts only: Tilt sensor off Green LED flashes once; orange LED three times.
LED for battery status	 If instrument is on and connected to the charger: Green LED flashes 1x: Battery is charged to 25%. Green LED flashes 2x: Battery is charged to 50%. Green LED flashes 3x: Battery is charged to 75%. Green LED is on: Battery is fully charged.

LDM Laser

Status of Laser Beam		Description
	OFF	Pointfinder is OFF or 3D Disto targets automatically.
	ON	Pointfinder is ON or user is targeting by Remote Control.
010734_001	Flashing	To indicate the precise position of a projected point.

Remote Control Components



- a) Key ring
- b) Battery compartment
- c) DIST button
- d) Navigation buttons: Up/Down/Right/Left
- e) Control LED

Navigation Buttons

The RM100 Remote Control has five buttons that allow turning the 3D Disto and executing a distance measurement or point projection, depending on the application program running.

The RM100 Remote Control does not support the Tool Kit applications.

Targeting Procedure

- 1) **Rough targeting:** hold (a) / (v) / (b) to turn the 3D Disto as long as key is pressed.
- 2) **Fine targeting:** short tap on (a) / (v) / (b) to turn the 3D Disto by small single steps.
- 3) **Measure:** Press ...

2.4

Power Supply

First-time Use / Charging Batteries

- The battery must be charged prior to using it for the first time because it is delivered with an energy content as low as possible.
- The permissible temperature range for charging is between 0°C to +40°C/ +32°F to +104°F. For optimal charging, we recommend charging the batteries at a low ambient temperature of +10°C to +20°C/+50°F to +68°F if possible.
- It is normal for the battery to become warm during charging. Using the chargers recommended by Leica Geosystems, it is not possible to charge the battery if the temperature is too high.
- For new batteries or batteries that have been stored for a long time (> three months), it is effectual to make only one charge/discharge cycle.
- For Li-lon batteries, a single discharging and charging cycle is sufficient. We recommend carrying out the process when the battery capacity indicated on the charger or on a Leica Geosystems product deviates significantly from the actual battery capacity available.

Operation / Discharging

- Batteries can operate from -10°C to +50°C/14°F to +122°F.
- Low operating temperatures reduce the capacity that can be drawn; high operating temperatures reduce the service life of the battery.


3D Disto Power Supply

Only Leica Geosystems authorised service workshops are entitled to replace the battery socket.

- Internal: by battery socket, with non-removable Li-lon batteries, 14.4 V, 63 Wh.
- **External:** Power supply for 3D Disto connected by cable with country-specific plugs for worldwide use.

Input: 100 - 240 V AC, 50/60 Hz.


Output: 24 V DC, 2.5 A. Length: 1.80 m.



- a) Battery socket
- b) Power supply connector

RM100 Remote **Control Power** Supply

The RM100 is equipped with one AA alkaline battery, 1.5 V.



- 1) Push the battery cover in the direction of the arrow to open the battery compartment.
- 2) Replace the battery and refit the battery cover.

2.5

2.5.1

3D Disto Software

Software Concept

3D Disto System Software

The 3D Disto includes a user interface software for computers with Windows® operating systems.

Hardware requirements:

- Windows 7 and later. RT versions are not supported.
- Desktop devices or laptops with keyboard and mouse.
- Touchscreen devices and tablets.
- Screen resolution at least 680 x 1000 px
- 32 bit or 64 bit



Insert the Leica USB memory stick only into a USB port "Type A". For other port types, use an adapter. Ensure, that both the port and the adapter have "on-the-go" functionality (OTG).

License Key

To enable the 3D Disto applications, the software needs a licence key. Refer to the following list for information about where to find the licence keys:

- On the delivery papers or receipt from your dealer.
- On the USB memory stick (key file).
- On the Leica myWorld website after registering your product.

Activating Software Applications with the License Key

Entering the License Key Manually



Connect the 3D Disto to your Windows® device and start the 3D Disto software application.

1) On the main screen, press the Menu button.



- 2) Select **Device...** » **Software...** » **License...** » **Enter license keys**.
- 3) Enter the license key and press **OK**.



Importing the License Key

- 1) Click on the 3D Disto Data icon on your desktop.
- 2) Copy the license key file into the folder "license".

Customised Application Programs

Customised software, specific to user requirements, can be developed using the third-party software development environment. For further information, contact a Leica Geosystems representative.


Software Update

- 1) Start your internet browser and go to the myWorld homepage. (https://myworld.leica-geosystems.com)
- 2) Register your product by entering the equipment number.
- 3) Choose the myProducts page, choose the latest software version and press the **Download** key.

Home Screen



All shown screens are examples. It is possible that local software versions vary from the standard version.



- a) Result window with result choice key
- b) Title bar with Home key
- c) Toolbar
- d) Sketch area/Pointfinder
- e) Main operation bar
- f) 3D Disto position
- g) Status bar
- h) Navigation cube and tools

Element	Description
Title bar	Shows the running application.
	save and close files or running applications.
Main operation bar	Contains the following buttons:
	Menu Opens the menu to start applications or to define settings.
	DIST button
	Pointfinder Opens, closes and locks Pointfinder. These keys are displayed during all applications.
Sketch area	Displays measured points, lines and areas and correct position of 3D Disto in relation to measured points - either in foot print or unfold mode/face mode.
Pointfinder	Shows 3D Disto live video stream used to target points and to take pictures.
Results window	Displays all results such as distances, heights, slopes, areas, angles together with the corresponding result choice key, for example
Toolbar	Contains application-specific tool keys. Refer to " Toolbar of the Standard Application (Measure)".
Status bar	Displays status of connections, batteries, running function mode and assistant support.
Navigation cube and tools	Changes perspective and scale of the sketch. Click on a face, a corner or an edge of the cube for pre-defined views. Use the navigation tools to adjust the view individually.

Operating Principles for the Sketch View

Selecting or Drawing Items

Ensure, that the navigation tools are deactivated.

To select a point or line in the sketch, click with the mouse or tap with one finger. To draw a line, select a point with mouse, stylus or finger, slide to the desired point and release.

Adjusting the Sketch View with Navigation Tools

Use the navigation tools to adjust the sketch view individually.



- Zoom by drawing a rectangular area
- Zoom
- · Fit the whole model into the view
- · Pan the sketch
- Rotate the sketch
- Change the perspective

To activate a navigation tool, click or tap on it. *The selected tool is highlighted and the cursor changes.*

To deactivate a tool, click or tap on it again.

Adjusting the Sketch View with the Navigation Cube

You can also use the navigation cube to adjust the sketch view. Click and drag the cube to adjust the view individually.


Click on a face, a corner or an edge of the cube for pre-defined views.



Gestures for Touch-Screen

If your device has a touch screen, you can use two-finger gestures for quickly adjusting the sketch view without using the navigation tools:

Swipe:



Zoom in:



Rotate:



Zoom out:



Toolbar of the Standard Application (Measure)

Key	Description
•	Enter and measure a reference height.
<u> </u>	Start a line or surface scan.
×	Disable line drawing.
•44	Go one point backward.
>> •	Go one point forward.
/ /	Confirm the current operation.
&	Start area or volume mode.
\sim	Undo or redo last command.
	Clear functions.

Status Bar

Icon	Description
	Indicates remaining battery capacity for the 3D Disto.
Ų.	Indicates 3D Disto is connected to power supply.
•	Indicates USB connection between Windows device and 3D Disto.
R	Indicates WLAN connection is working.
0.5 m	Scale of sketch area and key to change zoom level.
28.	Indicates zoom level/magnification of Pointfinder.
브	Indicates tilt sensor is turned off.

Icons in the Result Window

Icon	Description
_	Horizontal Distance
/	Tie distance
▼ ⊿	Height, height difference
4	Left angle
∱	Right angle

	Description
<u></u>	Coordinates: X, Y and Z (Height)
	Tilt
\$	Horizontal/tilted area
00	Horizontal/titled area perimeter
	Volume height
ॐ	Volume
	Circle size
Ċ	Circumference
Ø	Diameter
	Scan area
凸	Scan perimeter
△	Scan volume
څ	Distance between point and plane.
+	Perpendicular distance of a point to the reference line.
	3D Disto 052
‡	Distance from the reference line base point to the foot of the perpendicular.

3 Instrument Setup

3.1 Setting Up 3D Disto

Setup Step-by-Step

The following description assumes setup on a tripod. You can also place the 3D Disto on flat surfaces such as floor or boards.

Step	Description	
	It is always recommended to shield the instrument from direct sunlight and avoid uneven temperatures around the instrument.	
1.	Set up the tripod in a suitable place where the points to be measured can be targeted well and extend the tripod legs to a comfortable working height.	2
2.	Place the 3D Disto onto the tripod head. Tighten the central tripod fixing screw.	
3.	Centre the circular bubble on the 3D Disto by adjusting the tripod legs.	1 1 1
4.	Press to turn on the instrument. 3D Disto starts self-levelling: the tilt is checked by a tilt sensor and the instrument levels itself if the tilt is < 3°.	010813,001
	Do not move the 3D Disto while self-levelling procedure is running.	


3.2

Connecting the 3D Disto to a Windows Device

Connect 3D Disto to a Windows Device Step-by-Step

Starting the Software

Step	Description		
1.	To start the software, click on the 3D Disto icon on your desktop.		
	When starting the software for the first time, the following screen is displayed:		
	Setup		
	Language: English - Slope: ± 0.00 % - Time format: 24h - Distance: 0.000 m - Time: 08:38 Angle: 360.000 ° - Date: 2015/07/02 Decim. separator: 1.00 -		
	✓		
	If necessary change the settings.		
	Press v to continue.		



3D Disto connected via USB cable

Step	Description
1.	To work with cable connection to 3D Disto plug in USB cable and press 📒 .


3D Disto connected via WLAN

Step	Description
	Depending on your Windows device it might be necessary to use the WLAN USB stick which is included in the delivery. For devices without a "Type A" USB port, use an adapter with "on-the-go" functionality.
1.	Plug the WLAN USB stick into the Windows device.
2.	To work with WLAN, press 🖳 .
	If connection failed, connect via USB cable as described above and change the WLAN channel in Menu » Device » WLAN channel . Within Menu » Device » Interfaces , select the WLAN USB stick. Then retry WLAN connection in Menu » Device » Connect 3D Disto.
	Change the WLAN channel if the connection is instable.

3.3 Assistant

Assistant and supporting icons

There is an assistant available that will guide you through all measurement tasks with illustrated pop-ups.



F

If not needed, it can be deactivated in **Menu » Settings » Assistant**. If assistant is deactivated there are still supporting icons in the status bar, showing which application is running and what user action is required.



26

3.4

Tilt Sensor

Tilt Sensor

A built-in tilt sensor ensures that measurements relate to true horizon or true plumb line, defined by gravity. The tilt is checked by a tilt sensor and the instrument levels itself if the tilt is $< 3^{\circ}$.



If 3D Disto cannot be levelled the 💆 in the status bar is blinking. Level the 3D Disto or cancel the levelling procedure.



For advanced users only:

If the tilt sensor is OFF the system does not compensate the tilt of the 3D Disto. All results that refer to a physically horizontal plane, for example tilt, height differences, horizontal distances, angles, areas, or volumes, now refer to the tilted horizon of the laser unit. Only the tie distance between two measured points is independent of the tilt sensor's setting. It can be useful to disable the tilt sensor in case of vibrations, for example on construction sites or in unstable or moving environments such as on boats. Almost all measurements can still be completed and exported data can be "levelled" afterwards by CAD software.

3.5

Device Configuration and Menu Settings

Device Configuration

All settings on the setup screen can also be changed through the menu: Choose Menu » Device.



- Connect 3D Disto to connect by WLAN, USB cable, or disconnect.
- **WLAN channel** to switch between different channels if connection does not work.
- **Tilt sensor** to activate/deactivate the tilt sensor. Choose **ON** when working in harsh construction environment with many shocks and vibrations, apart from that choose **ON** (sensitive).
- **Theft protection** to protect instrument with security PIN.
- **Calibration** to check and adjust. Refer to "8 Check & Adjust" for more information.
- **Software** to update software, to check software version or to enter/activate the software license key.

Settings

Press Menu » Settings, the following options appear:



- Snap Radius to define the area around a point/line. This setting offers a list of points that are very close to each other to simplify their selection.
- Assistant to activate/deactivate the assistant.
- Units to change the unit settings.
- **Welcome text** to enter for example company name.
- On-screen keyboard to define the display mode for the on-screen keyboard on your touch-screen devices.
 - Automatic: The on-screen keyboard is displayed automatically as soon as you are prompted to enter characters.
- **Date and time** to change date and time settings.
- **Language** to choose your preferred software language.
- **Import/Export** settings to change format, coordinates and list separator.
- The instrument has a **Reset** function. If you select the menu function **Reset to** default and confirm, the device returns to the factory settings. All measurement data is kept.

Data Management

File Manager

File Manager

The File Manager handles the entire data administration measurement files, photos Secure Points and data transfer.

To access the File Manager, press the **Menu** key 🔳 and select **File Manager**.



Description of keys:

Icon	Description
	Project folder
	Folder with photos
3	Folder with Secure Points
	Temporary file
	Measure file
	Projector file

Toolbar Keys within File Manager

Key	Function
仚	Close folder/File Manager
] <	Go to higher folder level or close File Manager
	Create a folder and enter a folder name
•	Scroll back
•	Scroll forward
✓	Open a selected file or folder
•	View the selected element.

Key	Function
	Data export. Refer to "3.6.2 Export and Import of Data".
	Rename file or folder
	Clear a selected file or folder.

Photo and Secure Points Administration

Photos and Secure Points are stored in separate folders.



3.6.2

Export and Import of Data

Data Export Step-by-Step

Step	Description	
	Export applies the distance unit setting to exported coordinates. This setting can be modified any time before an export is executed.	
	The import/export settings in the menu allow to set the coordinates of the first measured point of each application. This setting must be done before the first point in a new project (e. g. a new scan) is measured; the setting does not apply retrospectively.	
1.	Open File Manager, choose a folder or file and press .	
	 A key press on penerates a package of export files: DXF and DWG files: 2D, 3D, scale 1:1 CSV file: editable, common tabular data format TXT file: all results in editable ASCII format. Same content like CSV file JPG files of photos and Secure Points. 	
2.	Export data is transferred to the Export folder in the directory My Documents\Leica Geosystems\3D Disto on your PC.	


Data Import Step-by-Step

Step	Description
	It is possible to import DXF files or table formats for some applications.
	Data should be prepared on the PC before importing. Only points are imported, no lines. Remove irrelevant data such as frames, logos, coordinates, or orientation arrows in the DXF files before importing them.
1.	To access the Import folder, click on the 3D Disto Data icon on your desktop.
2.	Copy the CSV or DXF files to the Import folder.
3.	Refer to "6.3 Projector" for more information.

Calculator

Using calculator


- Tap on the result in the result window to start the calculator.
- Another option is to press Menu » Calculator.




Memory Function

The memory function allows you to add or subtract results, e.g. areas or volumes.

- Click **MC** to clear memory.
- Click **MR** to retrieve a value stored in memory.
- Click **M-** to subtract the displayed value from the value in memory.
- Click **M+** to add the displayed value to the value in memory.




Horizontal Angle



a) Horizontal angle: [°] or [gon]


Vertical Angle

Setting: Horizon = 0




a) Vertical angle: [°], [gon], [1:n] or [%]

Setting: Horizon = 90°/100 gon




a) Vertical angle: [°] or [gon]

Distances




a) Perpendicular distance




- a) Tie distance 🚄
- b) Vertical distance **◄** = height difference


Areas



- a) Tilted area, as measured
- b) Horizontal area, calculated by 3D Disto

References





a) Reference height:

A level that all heights refer to.

a) Reference axis/line:

A line that all dimensions refer to.

Tilt Sensor

The tilt sensor guarantees correct results even if the 3D Disto is not set up horizontally.




Tilt sensor off = disabled All measurement results relate to the **tilted axis and horizon** of the 3D Disto.



Tilt sensor on = enabled All measurement results relate to the **horizontal axis and horizon** if the 3D Disto is set up between 0° and 3°.

Secure Points


Secure Points **link measurements to a coordinate system**. These reference points allow changing the 3D Disto location or continuing measurements at a later time, so that all measurements fit together perfectly.



Refer to "6.4 Location" for more information.

Layout or Projection

Design data in DXF and common table formats can be imported and used to lay out the corresponding points or grids.




Laser Distance Meter The laser distance meter (LDM) determines distances using a visible red laser beam.

Calibration

Calibration is a workflow to check and adjust the accuracy of the instrument. Refer to "8 Check & Adjust" for more information.

Ruler for offset points

The ruler for offset points is an accessory to measure inaccessible or hidden points.



a) Ruler for offset points

Operation

5.1 Measurements

Description

The 3D Disto is a combination of a precise laser distance meter (LDM) and angle encoders. Measurements are used to establish the relation between different targets, such as horizontal distances, tie distances, height differences to determine room dimensions, angles from wall to wall, areas, volumes, plumb points, or other features.

5.2

Pointfinder

Description

The 3D Disto has an integrated camera. It is accessible by @ and it shows the camera image directly on the 3D Disto display. The crosshairs in the Pointfinder image allow precise targeting and measuring even if the laser beam is not visible, for example over long distances or because of bright backlight conditions.

Example of a Pointfinder screen:



Using Pointfinder

Pointfinder Key

To start the Pointfinder, press



A second key press activates the lock mode, a third one unlock and closes Pointfinder.

A lock symbol on a key indicates the lock mode.



Targeting: There are different options to target a measurement point:







- a) Press the arrow keys on the screen for targeting, hold for fast 3D Disto turns and short taps for single step turns.
- b) Tap & Measure Targeting: tap on a position on the screen. Laser point turns to this point automatically.
- c) **Joystick Targeting**: is activated by long tap on the centre of the crosshairs. A red dot appears in the centre. Slide stylus on the screen to turn 3D Disto in this direction in real-time until red arrow is released. The longer the red arrow is, the faster the 3D Disto turns.


3D Disto, Operation

Toolbar description


Key	Function
⊕ ⊝	Press to zoom in or out.
*	Press to adjust the brightness of the camera.
☼ ••	Press to display/hide all measured points.
! %	Press to measure hidden points. Select an offset tool in the pop-up: • Vertical offset: Measure one point on any vertical target. • Individual offset: Measure two points on a pole or other hardware. • Offset ruler: Measure two points on the 3D Disto offset point ruler. An assistant leads through the workflow.
0	Press to take pictures for documentation purposes.
	Press in dark conditions to change Pointfinder picture to edge mode. Edges and corners will be highlighted in black.
(E)	 Press to choose between different turn commands: Turn 90° right Turn 90° left Turn ?°: Enter the horizontal angle by which the 3D Disto should turn. Horizon: 3D Disto goes to 0% slope in horizontal position. Plumb up: This option can be used to plumb up a point by setting up the 3D Disto exactly over it. Use the 90° markings on the 3D Disto socket for centring.

5.3 **Measurement Workflow**


Measurements step-by-step



sales@calcert.com




37



Areas & Volume Calculations

The 3D Disto can also help determine areas and volumes. Both can be determined during or after measuring.



sales@calcert.com

Step	Description
4.	Pop-up appears to choose between the different options to define the height:
	 Enter height: Enter a desired value and press OK. Measure height:
	Pointfinder opens, target and measure a point on floor with , followed by point on ceiling. You can measure the points anywhere on the floor or ceiling area. The height appears in the results window. • Close list: The result is an area.
5.	To change the height or to calculate the volume with a selected area press and proceed as described in the previous steps.
	and proceed as described in the previous steps.
6.	Quit application by pressing].

6 **Software Applications**

6.1 **Overview**

Description

There are a variety of software application programs available addressing a wide spectrum of construction tasks and facilitating daily work.

· Measure:

Provides practical features to measure room dimension, walls, windows, stairs and other details with reference height, manually or automatically.

Projector:

Enables layout of grids and other design data on floors, ceiling, or walls.

· Location:

Routine to easily and correctly check and relocate the position of the 3D Disto.

Tool Kit:

Smart measuring and set-out tools.

6.2 Measure

Description

This application program measures room dimensions, including details. For these measurements several additional features are available:

- Reference Height
- Single point measurement
- Scan tool for automated scans
- CAD tools

6.2.1 **Reference Height**

Define a Reference Height Step-by-Step


Within the measure application, you can define a known height as reference height. All further measured heights will refer to this reference height.

Step	Description
1.	Press 💌 .
2.	Pop-up prompts to enter and measure reference height. Enter the value and press OK .
	7 8 9 C
	4 5 6
	1 2 3
	± 0 .
	OK Cancel
3.	Pointfinder opens.
	Target the reference height and press 🙆.
4.	Reference height is displayed in the sketch area.

Description

This tool executes automated horizontal, vertical and slope profile measurements and surface scans.

Ideal for measuring rooms with non-square corners or curved walls, inaccessible points, slopes or areas.



Line Scan, step-bystep

Step	Description
1.	Press to start scan.
2.	Press to select line scans.
3.	Pop-up prompts scan types. Horizontal Vertical Slope
4.	Pointfinder opens to target and measure start point.
	Target and press 📵.
	For vertical line scan: Pop-up prompts to choose scan orientation: Perpendicular to wall Free: An assistant leads through the workflow.
5.	Pop-up prompts to define scan direction.
	Horizontal Line Scan: • Left (360°) • Point-to point • Right (360°)

Step Description Vertical Line Scan: Up (360°) Point-to point Down (360°) Slope Scan: Pointfinder opens. Target scan end and press 📵 . Pop-up window prompts to define spacing of the measurement. 6. Choose an interval and press **OK** or go to the rightmost position to enter individual intervals. Inlat Cancel For best scan results do not choose small intervals at long distances. 7. Press **OK**. Scan starts. Toolbar changes. Press • to start the camera. Press again to unlock. Press II to change scan spacing, skip the rest of the scan, continue scan, or cancel scan. Press •• to skip a scan point that you do not need or that causes problems. 8. If scan is finished pop-up prompts **Ready. Edit Scan? Yes/No.** 9. If Yes: New Toolbar appears, e.g. to measure missing points with DIST or delete unneeded points with Trash key Symbol. 0.050m 🚄 国のは中中国 (B) Press • ← or ▶ • to select points. Press 💉 to start a scan simplification that automatically clears aligned points. Press \checkmark to finish the scan.

1.888.610.7664

Step	Description
10.	Press to save and close measurement file.

Surface scan, stepby-step


Step	Description
1.	Press to start scan.
2.	Pop-up offers line scans and surface scans.
2.	Press for surface scan.
3.	Pop-up offers three scan options: horizontal, slope and vertical:
	Select your preference according to the surface you want to scan.
	Use vertical or horizontal scan to measure on walls, floor and ceiling.
	Slope scan is ideal to check the flatness of any surface, independent of its inclination.
4.	Select "precise" or "speedy" option. "Precise" finds the exact position of each scan point. "Speedy" prioritises short measuring time and robustness. Measurement accuracy is equal.
5.	 The Pointfinder opens for measurements to define the scan area: Define the Scan Area: horizontal & vertical: measure 2 edges (3 points). The area is completed automatically slope scan: measure the borders of the scan and press ✓ to continue.
6.	Pop-up window prompts to define spacing of the measurement. Choose an interval and press OK or go to the rightmost position to enter individual intervals.
	For best scan results do not choose small intervals at long distances.

Step	Description
7.	Press OK . Scan starts. The deviation of each scanned point to the reference plane is displayed in the result window.
	For geometric reasons, scan volume computation is an approximation.
	Toolbar changes.
	Press 👁 to start the camera. Press again to unlock.
	Press II to change scan spacing, skip the rest of the scan, continue scan, or cancel scan.
	Press 🖚 to skip a scan point that you do not need or that causes problems.
8.	Press to save and close measurement file.

6.2.3 **CAD Tools**

Description

CAD tools is a set of drawing functions. They appear as a submenu after a long tapon a line or point, like below:



If activated, the drawing icon ot is active in the status bar.

The following tools are available:

- Circle
- Rectangle
- Line Intersection
- Line Extension
- Point Shift
- Perpendicular Intersection


sales@calcert.com


Circle Tool

The circle tool's purpose is mainly to draw a circle on points like sockets or holes.

Step	Description
1.	Target and measure a point and activate circle function by a long tap on the point in the sketch area.
2.	Select Circle.
3.	Pop-up opens. 7 8 9 C 4 5 6 1 2 3 ± 0 . OK Cancel
	Enter the value and press OK .
4.	Circle is drawn around the chosen point. The results window contains radius, circumference and size of the circle.
	To clear the circle, enter 0 as value for the diameter or press

Rectangle Tool





Line Intersection Tool

The **Line Intersection tool** finds the intersection point between two lines.

Step	Description
	Intersection location is computed two-dimensionally in the X-Y plane. Intersection point height is computed by extrapolation of the first line.
1.	Target and measure two points or select an existing line.
2.	Activate CAD tools by a long tap on the line in the sketch area. Select Line Intersection .
3.	The assistant prompts for selecting a second line. Select a second line. The intersection point is proposed once a line is chosen:
4.	After was pressed, the intersection point is generated and the connecting lines to the existing points are added.
5.	


Line Extension Tool The **Line Extension tool** expands a line by a manually entered distance value.

Step	Description
	Line Extension end-point is computed as the 3-dimensional extrapolation of the selected line.
1.	Target and measure two points or select an existing line.
2.	Activate the CAD tools by a long tap on the line in the sketch are. Select Line Extension .
3.	The pop-up prompts for the extension length. Enter a value and press Ok . 7 8 9 C 4 5 6 1 2 3 ± 0 . OK Cancel
4.	The Line Extension end-point is proposed:
5.	After was pressed, the new point is generated and the connecting line to the previous point is added.
6.	31

Point Shift Tool

The **Point Shift tool** creates a new point by providing lateral movement value along an existing line, offset and offset angle.

Step	Description
	Point-shift location is computed two-dimensionally in the X-Y plane. New point height is computed by extrapolation of the selected line.
1.	Target and measure two points or select an existing line.
2.	Activate the CAD tools by a long tap on the line in the sketch area. Select Point Shift .
3.	Assistant and pop-up ask for the length movement. Enter a value and press OK .
4.	The length shifted point is proposed:
5.	Press to continue.
6.	Assistant and pop-up ask for the direction angle for the offset. Enter a value and press OK .
7.	The angle for offset direction is proposed:




section Tool

Perpendicular Inter- The **Perpendicular Intersection tool** finds the perpendicular projection of a point on the selected line.

Step	Description
	Intersection location is computed two-dimensionally in the X-Y plane. Intersection point height is computed by extrapolation of the first line.
1.	Target and measure two points or select an existing line.
2.	Activate the CAD tools by a long tap on the line in the sketch area. Select Perpendicular Intersection .
3.	The assistant asks for selecting a point. Press Ok . Select the point.
4.	The intersection point is proposed once a point is chosen:
5.	After was pressed, the intersection point is generated and the connecting lines to the existing point were added.
6.	

Description

This application projects points or geometrical grids onto a horizontal, vertical or sloped (= "free") plane. Design data in DXF or table format can be imported or a grid's geometry can be entered manually.



6.3.1 Workflow

Projector, Start

Step	Description
1.	Press Menu » Applications » Projector.
2.	A pop-up offers three scan modes: horizontal, slope and vertical. Select your preference according to the working area.
3.	Pointfinder opens to measure the working area.

Measure the Working Area

Step	Description
1.	Measure all important objects that you want to consider (edges, corners, etc.).
	For horizontal mode only: the first measured point defines the level that all following points refer to.
2.	If is enabled, press this key to close the outline. Then measure further
	points of interest (slope mode only).
3.	When all points are measured, press 🗸 to continue.

Point Design

Step	Description
1.	IMPORT IF
	A pop-up offers two options to define the projection points: Grid mode for a regular pattern and Import mode for individual DXF or CSV files.
	Use the key at any time to go back to the working area measurement.

Grid mode

Step	Description
1.	Press to start Grid mode.
2.	Grid design Define new Use last Measure Close list
	Pop-up appears to choose between Define new, Use last or Measure.
3.	 Select your preferred option: Define new: use the subsequent tools to enter the grid's geometry. Use last: restore the last grid design that was entered. Measure: follow the guided workflow to lock onto an existing grid. This option skips the following step Adjustment.


Import mode

Step	Description
1.	Press to start Import mode.
2.	The file manager displays all imported DXF and CSV files. Select a file.
	Pess of if you want to check the content via viewer. The head line of the viewer displays the dimension of the file. Change the setting for distance in the menu if the scale does not fit to the working area!
	To import points from a list, enter coordinates X, Y or Y; X in a text editor and save the file with extension CSV. If the import does not work properly check the Import/Export settings in the menu.
3.	Press to continue.
4.	Projection points are displayed and ready for adjustment.

Design Adjustment

Step	Description
	Use the key at any time to go back to Point Design.
1.	Aligner opens. 2.214m 3.1.
2.	The point design is now displayed in the working area and must be moved to the desired position. Use the following tools:
(hap	The grid can be moved up, down, left, and right on the screen in small steps using \$\cdot\cdot\cdot\cdot\cdot\cdot\cdot\cdot
3.	Press 🗸 to proceed.

Point projection



Plane Switching



If a point can not be projected on the ceiling, just move the laser beam onto the floor before pressing the **DIST** key. Following points will be projected on the floor from now on. The projection surface can be changed at any time.

6.3.2

Targeting and Layout with RM100 Remote Control

Functionality of the keys in Projector application



Press to activate laser and a second time to project or measure a point within the reference area.



Each arrow key selects the neighbouring point, turns the 3D Disto and starts the iterative measurement. Press once to activate the remote control and a second time to execute the command.

Description

The **Location** functions allow to change the position of the 3D Disto. **Secure Points** are placed by the user and make the positioning procedure easy.

Secure Location step-by-step

Step	Description
	You have to measure two points first before Secure Points can be saved.
1.	Label and affix three to five self-adhesive target marks on walls, ceiling or floor around your working area. Ensure that the target marks are spread out.
2.	Press Menu » Applications » Location » Secure Location . <i>Pointfinder opens.</i>
3.	Target the Target marks as precisely as possible and press 🔒 to measure.
	3D Disto takes a photo and saves it with coordinates, labelled with ID and date.
4.	Pop-up prompts Measure more Secure Points? Yes/No.
5.	Proceed as before and measure at least three Secure Points.
	You can add more Secure Points at any time.
	Ensure you have enough well-measured Secure Points around your working area. Even if one is lost there must be at least three for a successful relocation.
6.	After saving a minimum of three points you may leave the application by choosing No.

Relocation step-bystep

This feature allows the relocation of the 3D Disto into a defined coordinate system previously established by the **Secure Location** procedure, for example to complete a previous measurement.

Step	Description
	Use a 3D Disto position that allows targeting and measuring at least three Secure Points around your working area.
1.	Press Menu » Applications » Location » Relocate.
2.	A pop-up prompts you to define the tolerance.

Step	Description
(P	A lower tolerance increases the accuracy of your measurements and requires
*	precise aiming and visibility of the Secure Points.
	If there are no Secure Points available but your measurement must fit to the geometry of a previous one, just start your measurement with the same Base Line points. These are the first two points of a measurement.
3.	If Secure Points are available, folder opens.
	M123910002 M123910002 M123910002 M120910002 M120910_SP
	Choose a Secure Point by pressing ◀ / ▶ or by tapping on the screen.
	Press 👁 to enlarge.
	Press to see all Secure Points of the whole memory.
4.	Press ✓ to confirm point.
	Pointfinder opens.
5.	Target the target mark shown in the photo as precisely as possible and press
	to measure.
	If successful, pop-up appears Measure next Secure Point? Yes/Cancel.
6.	If Yes : Folder opens to choose next Secure Point. Proceed as described previously for the second and third Secure Point.
	If the first two Secure Points were measured successfully the 3D Disto roughly turns to the next chosen Secure Point. You just have to do the fine targeting and press .
7.	When you have measured three points successfully a pow-up shows OK . Measure more Secure Points? Yes/No/Cancel.
	 Press Yes to continue and proceed as described previously.
	• Press No to finish.
	If successful, a pop-up displays the dimensions between old and new position: XXXm ; Height: XXXm ; OK/Cancel . Accept with OK or Cancel to measure further points.
	If Relocation was not successful, pop-up prompts Out of tolerance!
	Measure more Secure Points? Yes/No/Cancel. Go on as described previously.
8.	Press to close the application.

Location Check step-by-step

If the 3D Disto was unintentionally moved, for example got bumped, the geometry of the measured points will no longer fit with that of the previously measured points. Start a Location Check to sustain the current accuracy/geometry.

Step	Description
1.	To initiate a Location Check press Menu » Applications » Location » Check Location .
2.	If Secure Points are available, select Secure Point and press \checkmark .
3.	The 3D Disto will target the Secure Point automatically. Check laser point position with target mark. If the laser point does not target the centre of the target mark, a relocation is recommended.
4.	Proceed that way for checking further points.
5.	Press to close Secure Point gallery.

6.5 Tool Kit

General

In addition to the standard applications this program features:




- · Comfort Plumbing,
- Comfort Targeting,
- Comfort Level,
- Meter Mark,
- · Height Tracking, and
- Parallel Line.

After each layout task the respective tool has to be restarted. A pop-up offers to continue with the same reference or to measure a new one. Data is not stored and cannot be imported or exported. Remote Control functionality is not supported in these applications.

6.5.1 Comfort Plumbing

Description

Comfort Plumbing allows plumbing any point up or down without standing above it.




Comfort plumbing step-by-step

Step	Description
1.	Start application in Menu » Applications » Tool Kit . The running application stays open in the background.
2.	Press on the Toolbar. Pointfinder opens.
3.	Target and measure the point to be plumbed. Press 🙆. Pointfinder stays open.
4.	Roughly target expected plumb and press . If plumb is found the laser flashes to indicate the exact position.
5.	Press 🚹 to close Tool Kit.

Comfort Targeting 6.5.2

Description

Comfort Targeting allows laying out a point relative to a reference point on vertical surfaces.




Use this tool only on vertical surfaces. On tilted surfaces, the layout position will not be correct.

Comfort targeting step-by-step

Step	Description
1.	Start application in Menu » Applications » Tool Kit . The running application stays open in the background.
2.	Press on the toolbar. Pointfinder opens.
3.	Target reference point on the wall. Press 🚳.
4.	Pop-up prompts to enter value for left or right distance to reference point. For left turn set a negative value. Enter 0 to lay out points with only vertical offsets to the reference point. Press OK to confirm the value. Laser point flashes to indicate exact position.
5.	Pop-up appears to enter vertical value (= distance above/below layout point). Default value = 0. Set a negative value for down turn. Press OK to confirm the value. 3D Disto turns and lays out the correct position. Laser point flashes to indicate exact position.
6.	Press 🟠 to close Tool Kit.

Description

Comfort levelling keeps the laser point at the same level when you turn the 3D Disto horizontally.



Comfort levelling step-by-step


Step	Description
1.	Start application in Menu » Applications » Tool Kit . The running application stays open in the background.
2.	Press on the toolbar. Pointfinder opens.
3.	Target reference height on the wall. Press 🔒 . Pointfinder stays open.
4.	Roughly target the assumed layout point and press 🔒 . Laser point flashes to indicate exact height position.
5.	Press 🟠 to close Tool Kit.

6.5.4 Meter Mark

Description

The **Meter Mark** tool refers to a meter mark or reference height and allows laying out any desired height.

This tool can be very helpful to mark the meter mark at several places in a room or lay out heights on several building levels.



Meter mark stepby-step


Step	Description			
1.	Start application in Menu » Applications » Tool Kit . The running application stays open in the background.			
2.	Press on the toolbar.			
3.	Pop-up prompts to enter the height and measure that reference height.			
4.	Pointfinder opens.			
	Target reference point on the wall. Press 📵.			
5.	Pop-up prompts to enter an absolute height to be laid out.			
6.	Pointfinder opens.			
	Roughly target close to expected absolute height on the wall. Press 📵.			
	Laser point flashes to indicate exact position of the absolute height.			
7.	Press 🏠 to close Tool Kit.			

6.5.5 **Height Tracking**

Description

Height Tracking allows determination of the height of a target that cannot be measured directly.

This tool can be very helpful for measuring the height of a tree or of power lines.




Height tracking step-by-step

Step	Description	
1.	Start Application in Menu » Applications » Tool Kit . The running application stays open in the background.	
2.	Press on the toolbar. Pointfinder opens.	
3.	Target and measure a reference point at the same horizontal distance as the point you would like to measure indirectly. Pointfinder stays open and measured point is displayed.	
	Do not move the 3D Disto horizontally too much after reference point has been measured, otherwise the result will be incorrect.	
4.	Target the point you would like to measure indirectly as exact as possible. The height difference to the reference point is displayed and updated in real-time in the results window.	
5.	Close the Pointfinder to finish the application.	

Parallel Line

Description

Parallel line allows laying out lines parallel to a reference line on walls, floors, or tilted surfaces.



Parallel Line stepby-step

Step	Description			
1.	Start application in Menu » Applications » Tool Kit . The running application stays open in the background.			
2.	Press on the toolbar.			
	Pointfinder opens.			
	All points have to be measured on the same surface.			
3.	Target and measure start and end point of the reference line.			
4.	A pop-up prompts to enter parallel distance to the left or right of the reference line. Press OK to confirm the entered value.			
5.	Pointfinder opens to roughly target layout point.			
	Press 📵.			
	Laser point flashes to indicate the exact position on the parallel.			
6.	Press 🟠 to close Tool Kit.			

Error messages and advice

Error No.	Advice		
150	Working range was exceeded.		
151	Invalid measurement.		
152	Change the 3D Disto position or use ruler for offset points.		
160	Repeat and do not move the ruler between both measurements.		
161	In some cases the Offset Point tool can not be used.		
170	Restart 3D Disto if the problem persists.		
171	Check all devices, for example power supply or cables, and try again.		
240	Tilt sensor calibration was not successful. System accuracy is at risk. Contact your distributor or Leica Geosystems representative.		
241	Too much drift. Repeat calibration precisely.		
243	Set up the instrument stably. Do not touch or rotate the 3D Disto. Repeat calibration.		
300	Select a horizontal line.		
350	Check projection surface. Laser could not reach the correct position.		
755	Point cannot be measured. Try different position. Tool does not work on horizontal planes.		
760	Point cannot be measured. Enter different values. Tool does not work on horizontal planes.		
765	Point cannot be measured. Try different position or enter different value. Tool does not work on horizontal planes.		
800	Data import or export is not possible.		
801	Not enough memory on USB stick.		
802	Storage device does not work properly.		
803	Check file condition and content.		
804	File or Folder write-protected or damaged.		
900	3D Disto error. Contact your distributor or Leica Geosystems representative if the error repeats.		
901	The reflected laser signal is too low.		
902	The reflected laser signal is too high.		
903	Too much background light.		
904	Laser beam interrupted. Repeat measurement.		
950	Execute Location Check to retain accuracy!		
951	3D Disto tilt is over 3°. Set up horizontally!		
952	Check 3D Disto, check for obstacles interrupting WLAN connection, or move towards 3D Disto.		
953	Check connection and cable.		
954	Plug in cable or choose "WLAN" in the menu.		
955	3D Disto temperature out of working range.		
956	Too much vibration or permanent movement.		
998	Contact your distributor or Leica Geosystems representative.		
999	Contact your distributor or Leica Geosystems representative.		

8 Check & Adjust

8.1 Overview


Description

Leica Geosystems instruments are manufactured, assembled and adjusted to the best possible quality. Quick temperature changes, shock or stress can cause deviations and decrease the instrument accuracy. It is therefore recommended to check and adjust the instrument from time to time. This check and adjust can be done in the field by running through specific measurement procedures. The procedures are guided and must be followed carefully and precisely as described in the following chapters. Some other instrument errors and mechanical parts can be adjusted mechanically.

Electronic adjustment

The following instrument errors can be checked and adjusted electronically:

- Crosshairs offset
- V-index
- Tilt sensor






During the manufacturing process, the instrument errors are carefully determined and set to zero. As mentioned previously, these errors can change and it is highly recommended to redetermine them in the following situations:

- After rough or long transportation
- After long storage periods
- If the temperature difference between the current environment and at the last calibration is more than 20°C

8.2 Tilt Sensor Calibration


Description

Before Calibration:



a) Tilt sensor offset

After Calibration:



Adjustment stepby-step


Step	Description
	This calibration is done automatically. You must only ensure that the 3D Disto is set up $<$ 3 $^{\circ}$.
1.	Calibration is started in Menu » Device » Calibration.
2.	Press
3.	3D Disto starts self-levelling automatically: the tilt is checked and the instrument levels itself if the tilt is < 3°.
	Pop-up prompts Don't touch 3D Disto about 1 minute!
4.	If ok , pop-up prompts Calibration successful.


Crosshairs Offset

Description

The laser point and the crosshairs in the Pointfinder do not coincide.

Before Calibration:





- a) Crosshairs
- b) Laser point

Adjustment stepby-step

Step	Description
1.	Calibration is started in Menu » Device » Calibration.
2.	Press
3.	Pointfinder opens. Place a target mark at a distance >25 m.
4.	Now aim at the target mark as precisely as possible. Press 😝 when the red laser spot is exactly on the target.
5.	Pointfinder stays open and red crosshairs are displayed. Move crosshairs to the centre of target mark as precisely as possible with the arrow keys. Press again.
6.	If in tolerance, pop-up appears with Set new: x=px; y=px, Reset to factory default , or Cancel calibration .
7.	Choose Set or Reset to adjust crosshairs. Final pop-up asks Are you sure? Yes/Cancel.
8.	If Yes , checkmark is displayed to confirm parameters were set successfully.

8.4 V-Index Error


Description

The vertical index does not coincide with the standing axis.




Tilt sensor calibration followed by a crosshairs calibration is recommended before starting V-Index calibration! Refer to "8.2 Tilt Sensor Calibration" and "8.3 Crosshairs Offset".

Before Calibration:



- a) Height error
- b) Vertical angle offset

After Calibration:



Adjustment stepby-step

	I=			
Step	Description			
1.	Set up the 3D Disto close to a wall with a steep target of good visibility that is at least 15 m above the instrument.			
2.	Calibration is started in Menu » Device » Calibration.			
3.	Press 👱 .			
4.	Pointfinder opens.			
	Target as precisely as possible.			
5.	Press 🙆 .			
6.	3D Disto turns to second face automatically.			
	Target a second time. Press .			
7.	If both measurements were successful, a pop-up window appears with Set			
	new: XXX gon, Reset to factory default, or Cancel calibration.			
8.	Choose Set or Reset to adjust V-index.			
9.	Final pop-up asks Are you sure? Yes/Cancel . If Yes, checkmark is displayed to confirm parameters were set successfully.			

Reset to Factory Settings 8.5

Reset to factory settings step-bystep

Step	Description			
1.	Calibration is started in Menu » Device » Calibration.			
2.	Press .			
	Pop-up appears Reset all calibration settings to factory default? Yes/No.			
3.	If Yes: all user-defined calibration settings are reset to factory default without further request.			

Description

The instrument can be protected by a **P**ersonal **I**dentification **N**umber. If the PIN protection is activated, the software will always prompt for a PIN code entry after starting up.

If the wrong PIN was entered three times, a PUK is required, which can be found on the instrument delivery papers. If the PUK code was entered correctly, the PIN code is set to default value "0" and the PIN protection is deactivated.

Contact your Leica Geosystems representative if you need a replacement PUK.

Activate PIN code step-by-step

Step	Description			
1.	Got to Menu » Device » Theft protection. Default setting is Off.			
2.	Press Enable to activate.			
3.	Enter your desired PIN code (3 to 8 character numeric or alpha).			
4.	Accept with Ok.			
	Now the instrument is protected against unauthorised use. The PIN code is required now after switching on the instrument, de-activating standby, or re-entering the PIN settings.			

Deactivate PIN code step-by-step

Step	Description
1.	Got to Menu » Device » Theft protection.
	Press Disable to deactivate.
2.	Enter your PIN code and press OK to accept.
	The instrument is no longer protected against unauthorised use.

10

Care and Transport

10.1

Transport

Transport in the field

When transporting the equipment in the field, always make sure that you

- either carry the product in its original transport container,
- or carry the tripod with its legs splayed across your shoulder, keeping the attached product upright.

Transport in a road vehicle

Never carry the product loose in a road vehicle, as it can be affected by shock and vibration. Always carry the product in its transport container, original packaging or equivalent and secure it.

Shipping

When transporting the product by rail, air or sea, always use the complete original Leica Geosystems packaging, transport container and cardboard box, or its equivalent, to protect against shock and vibration.

Shipping, transport of batteries

When transporting or shipping batteries, the person responsible for the product must ensure that the applicable national and international rules and regulations are observed. Before transportation or shipping, contact your local passenger or freight transport company.

Field adjustment

Periodically carry out test measurements and perform the field adjustments indicated in the User Manual, particularly after the product has been dropped, stored for long periods or transported.

10.2

Storage

Product

Respect the temperature limits when storing the equipment, particularly in summer if the equipment is inside a vehicle. Refer to "11 Technical Data" for information about temperature limits.

Field adjustment

After long periods of storage inspect the field adjustment parameters given in this user manual before using the product.

Li-Ion batteries

- Refer to "Technical Data" for information about storage temperature range.
- Remove batteries from the product and the charger before storing.
- After storage recharge batteries before using.
- Protect batteries from damp and wetness. Wet or damp batteries must be dried before storing or use.
- A storage temperature range of 0°C to +30°C / +32°F to +86°F in a dry environment is recommended to minimize self-discharging of the battery.
- At the recommended storage temperature range, batteries containing a 30% to 50% charge can be stored for up to one year. After this storage period the batteries must be recharged.

10.3

Cleaning and Drying

Housing and Optical Components

- Blow dust off housing and optical components such as lenses or windows.
- Never touch the glass with your fingers.
- Use only a clean, soft, lint-free cloth for cleaning. If necessary, moisten the cloth with water or pure alcohol. Do not use other liquids; these may attack the polymer components.

Damp products

Dry the product, the transport container, the foam inserts and the accessories at a temperature not greater than $40^{\circ}\text{C}/104^{\circ}\text{F}$ and clean them. Do not repack until everything is dry. Always close the transport container when using in the field.

Cables and plugs

Keep plugs clean and dry. Blow away any dirt lodged in the plugs of the connecting cables.

11 **Technical Data**

11.1 **Technical Data**

Accuracy	Tie
Distance	(3D)

	at 10 m	at 30 m	at 50 m
Combination of angle and distance measurement	ca. 1 mm	ca. 2 mm	ca. 4 mm

Angle Measurement (Hz/V)

Horizontal 360°, Vertical 250° Working range:

Accuracy 5" (1.2 mm at 50 m)

Characteristics laser distance meter

System analyser basis 100 MHz - 150 MHz Measuring system:

Coaxial, visible red laser Type:

Working range: 0.5 m - 50 m

Laser class:

Laser point size (at 10 m): ~7 mm x 7 mm Laser point size (at 30 m): ~9 mm x 15 mm

Tilt Sensor Self-levelling range: $\pm 3^{\circ}$

10" (2.5 mm at 50 m) Accuracy:

Pointfinder Zoom (Magnification): 1x, 2x, 4x, 8x

Field of view (at 10 m): 1x: 3.40 m x 2.14 m

2x: 1.70 m x 1.07 m 4x: 0.85 m x 0.54 m 8x: 0.42 m x 0.27 m

Circular bubble sensitivity

1°/mm

Operation **Buttons:** ON/OFF Button

> Ports: USB Type B, power supply plug-in

Communication

Data transfer: USB Type A, WLAN

Wireless technology: SD Card, range 50 m (depending on the environment),

11 channels

Supported data formats: Import: DXF, CSV

Export: DXF, TXT, CSV, JPG, DWG

Power

Internal:

Type: Li-Ion battery Voltage: 14.4 V 63 Wh

Charging time: 8 h Typical operating time 8 h

External:

Voltage: 24 VDC, 2.5 A

Mounting 5/8" thread Instrument dimensions

186.6 mm x 215.5 mm (diameter x height)

Weight

2.8 kg

Environmental specifications

Temperature

Operating temperature: -10°C to +50°C Storage temperature: -25°C to +70°C

Protection against dust, sand and water

IP54 (IEC60529)

Humidity

Protection: Max 85 % r.h. non-condensing

RM100 Remote Control

Range: 30 m (depending on environment and operation conditions)

Communication: Infrared (IR) 1 AA, 1.5 V Battery

11.2

Conformity to National Regulations

Conformity to national regulations

• FCC Part 15, 22 and 24 (applicable in US).

Hereby, Leica Geosystems AG, declares that the 3D Disto and the RM100 are in compliance with the essential requirements and other relevant provisions of Directive 1999/5/EC and other applicable European Directives. The declaration of conformity may be consulted at http://www.leica-geosystems.com/ce.



Class 1 equipment according European Directive 1999/5/EC (R&TTE) can be placed on the market and be put into service without restrictions in any EEA Member state.

- The conformity for countries with other national regulations not covered by the FCC part 15, 22 and 24 or European directive 1999/5/EC has to be approved prior to use and operation.
- Japanese Radio Law and Japanese Telecommunications Business Law Compliance.
 - This device is granted pursuant to the Japanese Radio Law and the Japanese Telecommunications Business Law.
 - This device should not be modified (otherwise the granted designation number will become invalid).