

1.888.610.7664



www.calcert.com

sales@calcert.com

SPECIFICATIONS

Range: -58 to 572 °F and -50 to 300 °C

Resolution: 0.1° from -20° to 2
1° otherwise

Accuracy: ±1° C from -20° to 20°
(Model 4370)
±0.4° C at tested temperature
(Model 4369 Ultra)

ULTRA™ THERMOMETER ACCURACY

Ultra™ thermometers are tested at selected test points to be within tighter than normal tolerances to assist in providing improved accuracy. Other points will not necessarily fall within the same accuracy as those found at the selected test points, but will be within an accuracy of ±1° C.

OPERATION

1. Press the ON/OFF button to turn the unit on. Press the °F/°C button to switch between Fahrenheit and Celsius.
2. Insert the probe into the material to be measured and read the display.
3. Press the ON/OFF button to turn the unit off. To conserve battery life, always turn the unit off when not in use.

ALL OPERATIONAL DIFFICULTIES

If this thermometer does not function properly for any reason, replace the battery with a new high quality battery (see the "Battery Replacement" section). Low battery power can occasionally cause any number of "apparent" operational difficulties. Replacing the battery with a new fresh battery will solve most difficulties.

**TRACEABLE
FOOD/
WATERPROOF/
PIERCING/
DROP-PROOF
THERMOMETER
INSTRUCTIONS**

 Control Company Cat. No. 4369 & 4370

Traceable® and Ultra™ are registered trademarks/trademarks of  Control Company.

© 2008 