PT-500 Analog Output Series User Manual

4-20 mA, 0-5 VDC, 0-10 VDC, mV/V





Table of Contents

Introduction	iii
Warranty and Warranty Restrictions	iv
Chapter 1: Specifications and Options	1
Dimensions	1
Specifications	
Model Number Configurator	
Electrical Pinout Table and Supply Power Table	4
Chapter 2: Installation and Removal Procedures and Notes	4
Tools Needed	
Mounting Instructions	
Electrical Installation	
Removal Instructions	
Chapter 3: Maintenance	5
General Care	
Zero Adjust	
Vent Tube Drying	
Repair and Returns	
Chapter 4: Hazardous Location Installation and Certification	8
Intrinsically Safe Wiring Diagram	8
Non-Incendive Wiring Diagrams	9
CSA Certificate of Compliance	

Introduction

Thank you for purchasing a PT-500 Analog Output series submersible pressure transmitter from APG. We appreciate your business! Please take a few minutes to familiarize yourself with your PT-500 and this manual.

PT-500 submersible pressure transmitters offer reliability in harsh industrial conditions and hazardous locations. The 4-20 mA model is certified intrinsically safe for hazardous areas in the US and Canada by CSA for Class I, Division 2, Groups C and D, Class I, Zone 2, Group IIB, and Class I, Division 1, Groups C and D, Class I, Zone 0, Group IIB environments. The small size, integrated electronics, wide operating temperature range, and durability make the PT-500 the perfect instrument for static and dynamic pressure measurement.

Reading your label

Every APG instrument comes with a label that includes the instrument's model number, part number, serial number, and a wiring pinout table. Please ensure that the part number and pinout table on your label match your order. The following electrical ratings and approvals are also listed on the label. Please refer to the Certificate of Compliance at the back of this manual for further details.

Electrical ratings

Input: 10 to 28 Volts DC; Output: 4-20 mA Exia Class I, Division 2; Groups C, D T4 Class I, Zone 2, Group IIB AEx nC IIB T4: Ta: -40°C to 85°C SEx nL IIB T4: Ta: -40°C to 85°C

Maximum Working Pressure: 10,000 PSI

Vmax $U_i = 28$ VDC, Imax $I_i = 110$ mA, Pmax $P_i = 0.77$ W, $C_i = 0$ µF, $L_i = 0$ µH Install in accordance with drawing 9002803, sheet 2 (page 9).

Input: 9 to 28 Volts DC; Output: 4-20mA Exia Class I, Division 1; Groups C, D T4 Class I, Zone 0, Group IIB AEx ia IIB T4: Ta: -40°C to 85°C $^{
m JS}$ Ex ia IIB T4: Ta: -40°C to 85°C

Maxium Working Pressure: 10,000 PSI


Vmax U_i = 28VDC, Imax I_i = 110mA, Pmax P_i = 0.77W, C_i = 0.042 μ F, L_i = 0.320 μ H Install in accordance with drawing 9002803, sheet 1 (page 8).

1 IMPORTANT: Your 4-20 mA PT-500 MUST be installed according to drawing 9002803 (Intrinsically Safe Wiring Diagram or Non-Incendive Wiring Diagram) as indicated above to meet listed approvals. Faulty installation will invalidate all safety approvals and ratings.


APG# www.calcert.com 1.888.610.7664

Chapter 1: Specifications and Options


Dimensions




PT-500 with Reusable Cage



PT-500 with Welded Anti-snag Cage



PT-500 with Tri-clover Sanitary Fitting



PT-500 with Removable Plastic Nose Cone

APG∰.

1.888.610.7664

Specifications

Performance

Pressure Ranges 0 to 300 PSIG

Analog Outputs 4-20mA, 0-5VDC, 0-10VDC, mV/V

2X FSO Over Pressure **Burst Pressure** 3.0X FSO 1 Year Stability 0.75% FSO

Accuracy

Linearity, Hystereses & Repeatability ±0.25% of Full Scale (BFSL) up to ±0.1% of Full Scale

Thermal Zero Shift @ 70 °F ±0.045% FSO/°C (±0.025% FSO/°F) Thermal Span Shift @ 70 °F ±0.045% FSO/°C (±0.025% FSO/°F)

Environmental

Operating Temperature -40 to 85°C (-40 to 185°F) Compensated Temperature -17 to 54°C (0 to 130°F) Maximum Submersible Depth 462.2 ft / 140.88 m / 300 psig

Electrical

Supply Voltage (at sensor) 4-20 mA: 9-28 VDC 0-10 VDC: 14-28 VDC

0-5 VDC: 9-28 VDC mV/V: 10 VDC*

Output Signal @ 21°C 3-30 mA max.

Reverse Polarity and Surge (per IEC 61000-4-5) Protection $R_{(max)} = ((V_s-12V)/0.02A)-(0.042\Omega \text{ per ft. of cable})$ Load Limitation Startup Time 4-20 mA: 100 ms 0-10 VDC: 300 ms

0-5 VDC: 300 ms

0-10 VDC: 3 mA **Current Draw** 4-20 mA: 3-30 mA

0-5 VDC: 3 mA

Materials of Construction

Wetted Materials 316L Stainless Steel Anti-snag Cage 316L Stainless Steel Cable Urethane, PVC, or Hytrel

Protective Nose Cone Delrin Viton ETP-s Seal

Mechanical

Pressure Connection See model number configurator for complete list Up to 200 pounds Cable Tensile Strength

Patents

US Patent No. 7,787,330

*mV/V output is calibrated to 10 VDC input.

Model Number Configurator

A. Cable Type

- □ Urethane Blue (with vent tube)
- □ **A** PVC Black (no vent tube sealed unit)
- □ **B** Hytrel .31" Ø Black (with vent tube)
- □ **C** PVC Black (with vent tube)
- □ **D** Hytrel .25" Ø Black (with vent tube)

B. Pressure Range

□ Specify range in desired unit of measure

_____ Max Water Depth 462.2 ft. (140.9 m), 300 psig

C. Standard Units of Measure

- □ PSI □ FTH2O □ INWC
- □ INH2O □ MMH2O □ FWC

D. Output

- □ **L1** 4-20 mA, 2-wire
- □ **L3** 0-5V, 4-wire*
- □ **L9** 10 mV/V, 4-wire*
- □ **L10** 0-10V, 4-wire*
- □ **L5** Modbus RTU, 4-wire RS-485* Pressure reading only
- □ **L31** Modbus RTU, 4-wire RS-485 * Level calculations, tank volume

E. NPTM

- □ **E0** 1/2" NPTM fitting for conduit, with pigtail
- □ **E5** Pigtail without conduit connection

F. Process Connection

- □ P1 1/2" NPTM with removable plastic nose cone
- □ **P5** 1/4" NPTF
- □ **P37** Welded Cage (anti-snag 1 piece fitting)
- □ **P38** 1-1/2" tri-clover with 3/4" diaphragm
- □ **P39** Reusable Cage (includes P38 fitting)

G. Cable Length

□ (specify length of cable needed in feet)

H. Accuracy

- □ **N0** ±0.25%
- □ **N1** ±0.25% with NIST certification
- □ **N2** ±0.1% with NIST certification

Note: ▲Indicates this option is standard.

Note: *Indicates this option does not yet have CSA Approvals.

Electrical Pinout Table and Supply Power Table

PT-500 Analog Output Series Pin Out Table

		4-20 mA	Voltage		
Pigtail	Red	+ Power/Signal	+ Power		
	Black	- Power/Signal	- Power		
	Green	-	+ Out		
	White	-	- Out		
	Shield	Case Gnd	Case Gnd		

PT-500 Analog Output Series Supply Power Table

	4-20 mA	0-5 VDC	0-10 VDC	mV/V
Power Supply	9-28 VDC	9-28 VDC	14-28 VDC	10 VDC*

^{*} mV/V output calibrated to 10 VDC input

Chapter 2: Installation and Removal Procedures and Notes

Tools Needed

- Wrench sized appropriately for your PT-500's process or conduit connection.
- Thread tape or sealant compound for threaded connections.

Mounting Instructions

Your PT-500 can be mounted in three ways: via NPT process connection, free-hanging suspension, or conduit mounted. Mounting your pressure transducer is easy if you follow a few simple steps:

- Never over-tighten the sensor. This can compress the diaphragm, changing how it reacts to pressure. In all cases, tighten the sensor as little as possible to create an adequate seal. On straight threads, tighten only until you feel the o-ring compress - making sure you don't damage or extrude the o-ring.
- Always use thread tape or sealant compound on tapered threads. Wrap thread tape in the opposite direction of the threads so it does not unravel as you screw the sensor into place. Unraveling can cause uneven distribution and seal failure. For straight threads use an o-ring.
- Always start screwing in your sensor by hand to avoid cross-threading. Thread failure can be a problem if you damage threads by over-tightening them or by crossing threads.
- For suspension mounting the PT-500, drill a 3/16" hole into the 1/2" NPTF to 1/2" NPTF hex coupler (P/N 511414) and secure it to the 1/2" NPTM coupler fitting of the PT-500. Attach a .060" diameter 316L SS cable of desired length to the hex coupler and secure the steel cable according to your application requirements.

Electrical Installation

• Attach the wires of your PT-500 to your control system according to the pinout table above.

NOTE: If your PT-500 has a vent tube, do not seal, cover, or close the vent tube with anything other than an APG-provided venting cap or desiccant drying cartridge (See Figure 4.1 and 4.2). Unapproved seals or covers will prevent proper sensor operation.

Removal Instructions

Removing your PT-500 from service must be done with care. It's easy to create an unsafe situation, or damage your sensor, if you are not careful to follow these guidelines:

- For sensors installed via NPT process connection, make sure the pressure is completely removed from the line or vessel. Follow any and all procedures for safely isolating any media contained inside the line or vessel.
- Remove the sensor with an appropriately sized wrench (per your process connection).
- For suspended sensors, retrieve the sensor from the vessel. Follow any and all procedures for safely isolating any media contained inside the line or vessel.
- Carefully clean the sensor's fitting and diaphragm of any debris (see General Care) and inspect for damage.
- Store your sensor in a dry place, at a temperature between -40° F and 180° F.

DANGER: Removing your process connected PT-500 Pressure Transmitter while there is still pressure in the line could result in injury or death.

Chapter 3: Maintenance

General Care

Your PT-500 series pressure transmitter is very low maintenance and will need little care as long as it is installed correctly. However, in general, you should:

- For process connected sensors, keep the transmitter and the area around it generally clean.
- Avoid applications for which the transmitter was not designed, such as extreme temperatures, contact with incompatible corrosive chemicals, or other damaging environments.
- Inspect the threads whenever you remove the transmitter from duty or change its location.
- Avoid touching the diaphragm. Contact with the diaphragm, especially with a tool, could permanently shift the output and ruin accuracy.
- Clean the diaphragm or the diaphragm bore only with extreme care. If using a tool is required, make sure it does not touch the diaphragm.

1 IMPORTANT: Any contact with the diaphragm can permanently damage the sensor. Use extreme caution.

APG#.

www.calcert.com

Zero Adjust (4-20 mA, 0-5 VDC, and 0-10 VDC only)

The zero output (4mA, or 0 VDC) can be adjusted by holding a magnet perpendicular to the can, approximately 1-1/2" from the top or bottom of the can.

Holding the magnet close to the top of the can increases the output (See Figure 3.1). Holding the magnet close to the bottom of the can decreases the output (See Figure 3.2).

If the zero output values do not change right away, hold the magnet in place near the top of the can until the values change, for up to two minutes. If there is no change, repeat the procedure near the bottom of the can. If there is still no change, consult the factory.

Unvented PT-500A transmitters do not automatically adjust to changes in barometric pressure. We recommend that PT-500A transmitters be zeroed upon receipt, and after major weather events.





Figure 3.1 Figure 3.2

NOTE: Span calibration must be done at the factory for all analog models.

Vent Tube Drying

Condensation in the vent tube can damage the electronics in your sensor, resulting in unreliable readings. APG offers two methods of preventing vent tube condensation: a venting cap, and a desiccant drying cartridge.

The venting cap is a PVC tube with a hydrophobic patch that allows moisture to pass out of the tube without allowing water in (See Figure 3.3). The cap is sealed by an o-ring, and is easily installed in the field.

The desiccant drying cartridge with vent tube adapter absorbs any moisture in the vent tube to keep vapor from condensing (See Figure 3.4). The installation of the desiccant drying cartridge is quick and easy. Common installation methods are cable tie, Velcro, and cable clamps.



Figure 3.3




Figure 3.4


- NOTE: Desiccant crystals change from blue to pink as they become saturated. Cartridge must be replaced when all crystals have saturated.
- **1** IMPORTANT: Do NOT use desiccant cartridge in the presence of vapors or liquids containing phosphate esters, synthetic lubricants, hydrocarbon solvents, methanol, acetone, lacquer solvents, or other organics.

Chapter 4: Hazardous Location Installation and Certification

Intrinsically Safe Wiring Diagram



Non-Incendive Wiring Diagram



CSA Certificate of Compliance



Certificate of Compliance

Certificate: 1984045 **Master Contract:**

Project: 2587208 **Date Issued:** December 17, 2012

Issued to: **Automation Products Group Inc**

> 1025 West 1700 North Logan, UT 84321

USA

Attention: Karl Reid

The products listed below are eligible to bear the CSA Mark shown with adjacent indicators 'C' and 'US' for Canada and US or with adjacent indicator 'US' for US only or without either indicator for Canada only.



Eshwar Kashyap

Issued by: Eshwar Kashyap

PRODUCTS

- PROCESS CONTROL EQUIPMENT - Intrinsically Safe and Non -CLASS 2258 03

Incendive Systems - For Hazardous Locations

CLASS 2258 83 - PROCESS CONTROL EQUIPMENT-Intrinsically Safe and Non-

Incendive - Systems-For Hazardous Locations-Certified to U.S. Standards

Class I, Div. 2, Groups C and D

Class I, Zone 2, Group IIB

Ex nL IIB T4; Ta: -40°C ... +85°C

AEx nC IIB T4; Ta: -40°C ... +85°C

Model PT-400-L1xxxx Pressure Transmitter. Rated 9-28VDC, 4-20mA. Maximum Ambient 85° C; Temperature Code T4; Maximum Working Pressure 10,000 PSI. Enclosure type: IP65. Installed as per Drawing 9002794. Non-Incendive with the following Entity Parameters:

Vmax, Ui = 28V

Imax, Ii = 110mA

Pmax, Pi = 0.77W

DQD 507 Rev. 2012-05-22



Certificate: 1984045 **Master Contract:** 237484

Project: 2587208 **Date Issued:** December 17, 2012

 $Ci = 0.055 \mu F$

 $Li = 7.95 \mu H$

• Model PT-400-L3/L10xxxx Pressure Transmitter. Rated 9-28VDC, 4-20mA or 0-5V, 20mA or 0-10V, 20mA; Maximum Ambient 85° C; Temperature Code T4; Maximum Working Pressure 10,000 PSI. Installed as per Drawing 9002794. Non-Incendive with the following Entity Parameters:

Vmax, Ui = 28V

Imax, Ii = 110mA

Pmax, Pi = 0.77W

 $Ci = 0\mu F$

 $Li = 0\mu H$

Model PT-500-xxxx Pressure Transmitter, Rated 10-28VDC, 4-20mA; Maximum Ambient 85° C; Temperature Code T4; Maximum Working Pressure 10,000 PSI; Non-Incendive with the following Entity Parameters:

Vmax, Ui = 28V

Imax, Ii = 110mA

Pmax, Pi = 0.77W

 $Ci = 0\mu F$

 $Li = 0\mu H$

Notes for Models PT-400, PT-500:

- 1. The "x" in the Model designations may be any alpha-numeric character, to denote minor mechanical options, not affecting safety.
- 2. These devices must be connected to a suitably certified and approved apparatus that provides non-incendive outputs either equal to or less than those as indicated by the applicable control drawings. This certified apparatus must be located in a safe area.

CLASS 2258 04 - Process Control Equipment - Intrinsically Safe, Entity - For Hazardous Locations

DQD 507 Rev. 2012-05-22

Page: 2

APG#

sales@calcert.com



Certificate: 1984045 **Master Contract:** 237484

Project: 2587208 **Date Issued:** December 17, 2012

CLASS 2258 84 - Process Control Equipment - Intrinsically Safe, Entity - For Hazardous Locations - Certified to US Standards

Class I, Div. 1, Groups C, D

Class I, Zone 0, Group IIB

Ex ia IIB T4; Ta: -40°C ... +85°C

AEx ia IIB T4; Ta: -40°C ... +85°C

Model PT-400-L1xxxx Pressure Transmitter. Rated 9-28VDC, 4-20mA. Maximum Working Pressure: 10,000 PSI. Installed as per Drawing 9002794. Ambient Range: -40°C to +85°C. Enclosure type: IP65. Intrinsically safe with the following entity parameters:

Vmax, Ui = 28V

Imax, Ii = 110mA

Pmax, Pi = 0.77W

 $Ci = 0.055 \mu F$

 $Li = 7.95 \mu H$

Model PT-500-xxxx Pressure Transmitter; Maximum Ambient 85° C; Temperature Code T4; Maximum Working Pressure 10,000 PSI; Entity parameters as follows: Vmax, Ui = 28V

Imax, Ii = 110mA

Pmax, Pi = 0.77W

 $Ci = 0.042 \mu F$

 $Li = 0.320 \mu H$

Notes for Models PT-400, PT-500:

- 1. The "x" in the Model designations may be any alpha-numeric character, to denote minor mechanical options, not affecting safety.
- 2. These devices must be connected to a NRTL approved safety barrier (located in a safe area).

DQD 507 Rev. 2012-05-22

Page: 3



Certificate: 1984045 **Master Contract:** 237484

Project: 2587208 **Date Issued:** December 17, 2012

APPLICABLE REQUIREMENTS

C22.2 No 0 - M1991	General Requirements - Canadian Electrical Code Part
	II.
C22.2 No 0.4 - M2004	Bonding and Grounding of Electrical Equipment
	(Protective Grounding).
C22.2 No 142 - M1987	Process Control Equipment.
C22.2 No 157 - M1992	Intrinsically Safe and Non-Incendive Equipment for
	Use in Hazardous Locations.
C22.2 No 213 - M1987	Non-Incendive Electrical Equipment for Use in Class I,
	Division 2 Hazardous Locations.
CAN/CSA-C22.2 No. 60079-0:11	Explosive Atmospheres - Part 0: Equipment - General
	requirements
CAN/CSA-C22.2 No. 60079-11:11	Explosive Atmospheres – Part 11: Equipment
	protection by intrinsic safety "i"
CAN/CSA-C22.2 No. 60079-15:12	Electrical apparatus for explosive gas atmospheres
	- Part 15: Construction, test and marking of type of
	protection "n" electrical apparatus
CAN/CSA-C22.2 No. 60529:05	Degrees of protection provided by enclosures (IP Code)
UL 508, 17th Edition	Industrial Control Equipment.
UL 913, 7Th Edition	Intrinsically Safe Apparatus and Associated Apparatus
	for use in Člass I, II, III, Division 1, Hazardous
	(Classified) Locations.
ANSI/ISA-12.12.01-2007	Nonincendive Electrical Equipment for Use in Class
	I and II, Division 2 and Class III, Divisions 1 and 2
	Hazardous (Classified) Locations
ANSI/UL 60079-0:09	Electrical Apparatus for Explosive Gas Atmospheres -
	Part 0: General Requirements
ANSI/UL 60079-11:09	Electrical apparatus for Explosive Gas Atmospheres -
	Part 11: Intrinsic Safety "i"
ANSI/UL 60079-15:09	Electrical apparatus for Explosive Gas Atmospheres -
	Part 15: Type of Protection "n"
ANSI/IEC 60529:2004	Degrees of Protection Provided by Enclosures (IP
	Code)

DQD 507 Rev. 2012-05-22 Page: 4