

1.888.610.7664

2

3

4


5

6


7

8

A



B




KIT COMPRISSES
1 X RED 3 PIECE 500mA KIT - 1003-159
1 X GREEN 3 PIECE 500mA KIT - 1003-160
1 x USER GUIDE - 2002-855

C





www.calcert.com


D



E





MEGGER SERIAL NUMBER (ITEM 6)
LABEL TO BE PLACED ON THE
BOTTOM OF BOX AS SHOWN.



USER GUIDE (ITEM 5) TO BE PLACED AGAINST BACK FACE
OF ACCESSORY BOX (ITEM 4) WITH PRODUCT NAME FACING
THE FRONT FACE OF THE BOX.

NOTES:

1. TAKE LEADS (ITEMS 1, 2) OUT OF PRE PACKED BAGS.
2. REMOVE FUSE HOLDER. FIT 500mA 30kA FUSE (ITEM 3)
3. RETIGHTEN FUSE HOLDER FINGER TIGHT.
4. PLACE NEATLY INTO ACCESSORY BOX.



Material	DIMENSIONS IN MILLIMETRES TOLERANCES UNLESS STATED NOMINAL ±0.5 TO 1 DECIMAL PLACE ±0.15 ANGULAR ±1° HOLES TO BS EN ISO 286-2 H11 INSPECTION DIMENSION			DO NOT SCALE IF IN DOUBT, ASK!	
Finish				Drawn by	Checked by
Weight	First used on	Document type		J.Yarwood	M.Pollard
150 g	LEADSETS	ASSEMBLY DRAWING			
			COLOUR TOLERANCE AS AGREED WITH SUPPLIER AND DEFINED VIA A MASTER SAMPLE	All materials used for this component MUST be RoHS compliant	RoHS <input checked="" type="checkbox"/>
			© MEGGER INSTRUMENTS LTD. Reproduction in whole or in part without prior permission from the copyright owner is strictly prohibited		PROVEN COMPLIANT
			Title	Part Number	