

228 Leakage **Current Tester**



Model 228 Special Purpose AC/DC Milliameter

Designed specifically to measure hazardous "Leakage Currents" or "Touch Currents" which may appear when a person touches the conductive surface of electrical or electronic equipment.

The 228 is designed around IEC990, ANSI and UL guidelines.

- True RMS Readings
- Reads in Measurement Indication Units (MIU) up to .005 MIU
- Output Allows Measurement of Peak Current in Non-Sinusoidal Wave Forms
- Let-Go, Reaction, and Burn Hazard Response Networks
- Detects dangerous AC & DC Leakage currents
- Includes Test Leads, Alligator Clips, Batteries and Manual

Ordering Information			
Leakage Tester	Catalog Number		
228 Leakage Current Tester	40027		
Accessories	Catalog Number		
Test Leads w/Screw-On Alligator Clips	00125		
Case, Black Padded Nylon Carrying	00834		
Optional carrying case includes convenient storage pouch for test leads and Operators Manual			



228 Leakage Current Tester

Specifications

The specifications apply to sinusoidal AC waveforms only.

Accuracy is not quaranteed for non-sinusoidal or complex waveforms.

Equivalent network component values Equivalent measuring instrument load Ranges Current accuracy Meter measurement method Meter frequency response DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Output frequency response DC to 50Hz	Reaction sponse Network De 1 MΩ - 10 pF , 1, 3, 10 M.I.U.	Let-Go Response Network signed around IEC 990 (ε 1 MΩ - 62 pF	Unweighted Burn Hazard Response Network excluding fuse)		
Equivalent network component values Equivalent measuring instrument load Ranges 0.3 Current accuracy Meter measurement method Meter frequency response DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Full Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	De 1 ΜΏ - 10 pF	signed around IEC 990 (e	•		
Equivalent measuring instrument load Ranges 0.3 Current accuracy Meter measurement method Meter frequency response DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Full Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	1 MΩ - 10 pF	,	excluding fuse)		
Ranges 0.3 Current accuracy Meter measurement method Meter frequency response DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Full Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2		1 MΩ - 62 pF	Designed around IEC 990 (excluding fuse)		
Current accuracy Meter measurement method Meter frequency response DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	, 1, 3, 10 M.I.U.		1 MΩ - 1 pF		
Meter measurement method Meter frequency response DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2		0.3, 1, 3, 10 M.I.U.	0-100 mA RMS		
Meter frequency response DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Full Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	±2% F.S. @ 60 Hz				
DC to 1 Hz 2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	True RMS				
2Hz to 19Hz (Accuracy not supported) 20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	(Relative to ANSI C101-1992 or UL-1459 2nd edition)				
20 Hz to 200 KHz 200 KHz to 1 MHz Output sensitivity Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	Pointer shall track within 5% of peak				
200 KHz to 1 MHz Output sensitivity Full Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2					
Output sensitivity Full Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	±2% F.S.	±2.5% F.S.	±2% F.S.		
Output accuracy Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	±2% F.S.	±2.5% F.S.	±5% F.S.		
Output frequency response DC to 50Hz 50 Hz to 100 kHz ±2	Full scale meter indication equals 1V RMS (Measured with a 1 $M\Omega$, 12 pF load)				
DC to 50Hz 50 Hz to 100 kHz ±2	±2% of reading @ 60 Hz				
50 Hz to 100 kHz ±2	(Relative to ANSI C101-1992 or UL-1459 2nd edition)				
	±2% of reading				
100 kHz to 200 kHz	.5% of reading	+2% / -3% of reading	±2% of reading		
100 KHZ 10 200 KHZ	±5% of reading				
200 kHz to 1 MHz	Accuracy not supported				
Voltmeter range	0-300 V (AC or DC)				
Voltmeter accuracy:					
DC to 1 Hz	Pointer shall track within 5% of peak				
2Hz to 19Hz (Accuracy not supported)					
20 Hz to 1KHz	±3% F.S. @ 60 Hz (Add ±1% for every additional 100 Hz)				
Voltmeter frequency response	DC to 1 KHz				
Power requirements	(2) 9V (NEDA 1604A) batteries				
Physical	7" x 5.25" x 3.125", 2-1/2 lbs (1.4kg), ABS plastic, fused input				
Environmental	27°C ±2° C, 70% non condensing relative humidity				
Maximum operating range	0° to 40° C				

Specifications subject to change without notice

Any discussion in this document regarding UL, ANSI or IEC specifications is for Reference purposes only.

The input network utilized in the M228 is detailed in Figures 1 through 3 on page 4 of the Manual. The customer is advised to obtain the latest specification from the rating agency.

NOTE: For specification information call ANSI at (212) 642-4900 or UL in Northbrook, IL at (847) 272-8800.