

FLOWMETER BATTERY PACK AND STAND TSI® MODEL 4199

OPERATION AND SERVICE MANUAL

1980504, REVISION D
FEBRUARY 2016



This battery pack works with the TSI Series 4000 and 4100 Flowmeters that have LCD displays. Flowmeters manufactured before August 2004 will not indicate low battery. For those meters, the meter will work properly until the display locks up; replace batteries at that time.

List of Components

1 - Battery pack	2 - 4000 Series lugs
2 - 4100 Series lugs	6 - AA batteries

Installation

Screw in both lugs to back side of flowmeter (the front being the display). 4000 and 4100 series flowmeters require different size lugs. Line up lugs with the holes on top of the battery pack. Press one lug in at a time. Attach cable to flowmeter.

Removal

Unplug power cable and then rotate the bottom of the meter away from the battery pack until lugs disengage from battery pack.



UNDERSTANDING, ACCELERATED

P/N 1980504 Rev D



1.888.610.7664



www.calcert.com

sales@calcert.com