

Traceable® Remote Alarm RH/Temperature Monitor

Triple display simultaneously shows min, max, and current humidity/temperature readings read from external probe

Remote humidity/temperature sensor on a 7-foot cable

- Hi/Lo Alarms, Min/Max memories
- High/low alarm feature may be set by user in 1% RH or 1° increments
- Perfect for use in hoods, classrooms, stockrooms, environmental chambers and chemical storage areas

Features:

- Monitors around-the-clock
- Meets quality-control needs, and critical experimental requirements
- Individually serialized, calibrated, and certified Traceable® to NIST

Displays:

- MIN/MAX and Current Probe Relative Humidity
- MIN/MAX and Current Ambient/Probe Temperature
- °F/°C switchable

Traceable to NIST for accuracy

Multi-point calibration on an individually-numbered Traceable® Certificate which assures accuracy from our ISO/IEC 17025:2005 (1750.01) calibration laboratory accredited by A2LA. It indicates traceability of measurements to the SI units through NIST or other recognized national measurement institutes (NMI) that are signatories to the CIPM Mutual Recognition Agreement.

Cat. No. 4154 Traceable® Remote Alarm RH/Temperature Monitor

Cat. No. 4155 Traceable® Alarm RH/Temperature Monitor (ambient only NO probe)



Convenient unit sits on bench, hung on the wall, or may be placed anywhere

Product Specifications

- ▶ **Humidity**
 - Range:** 5.0 to 95.0% RH
 - Resolution:** 0.1% RH
 - Accuracy:** ±3% RH from 25-75%, ±5% otherwise
- ▶ **Probe Temperature**
 - Range:** 0.0 to 60.0°C (32.0 to 140.0°F)
 - Resolution:** 0.1°
 - Accuracy:** ±0.5°C
- ▶ **Size:** 4¼ x ¾ x 2¾"
- ▶ **Weight:** 4 ounces
- ▶ **Supplied:** battery, external humidity/temperature sensor, flip-open stand, wall mount, Traceable® Certificate

TRACEABLE®
PRODUCTS

1.888.610.7664

 www.calcert.com

sales@calcert.com