

# 8" (203mm) Temperature Chart Recorder



# **Specifications**

Ambient Operating RH Conditions: 0-95% RH non-condensing (Recorder Only) **Ambient Operating Temperature Conditions:** 32.0 to 122.0F (0.0 to 50.0C)

**Approvals: CE** 

Battery Backup: Four AA Batteries (User Replaceable) Powers unit for up to 3 Days

Battery Life (Avg): 72 Hours (Back-up Only) Calibration Options: N100, N300, N400

**Channels:** CH1: Temperature

Chart Rotation Speed: 24 Hour, 7 Day or 31 Day

**Dimensions:** 3.1 x 9.2 x 9.2in **Display Dimensions Height: 1.375 Display Dimensions Width: 2.0** 

**Display Resolution: 0.1** 

**Display Type: LCD** 

Enclosure: Rugged Black ABS Case, Polycarbonate Door, Aluminum Dial

IP Rating: 20

Included Accessories: AC Adapter, Red Pen, Four AA Batteries, Replaceable Sensor, Quick Start Guide and 4' Bead-

Wire Probe. \*Charts sold separately.

**Keypad Functions:** Power On/Off, Pen Home

Mounting Options: Free Standing or Wall Mounted

Power Cord: 6 ft

Power Source: 120 to 240 VAC, 12 VDC (INTL fittings available); AC Adapter

Power Status Indicator: LED Indicator

Remote Sensor Length: 4

Remote Sensor Type: 1 K T/C with Mini Connector **Response Time:** 30 Seconds to 63% of Full Scale

Temperature Accuracy: +/-1.8F from -22.0 to 122.0F 3.8F (+/-1.0C from -30.0 to 50.0C 2.1C)



**Temperature Range:** -50.0 to 50.0F/C; -20.0 to 20.0F/C; 0.0 to 100.0F/C; 0.0 to 150.0F/C; 0.0 to 250.0F/C; 0.0 to

500.0F/C; 0.0 to 1000.0F/C (0.0 to 2000.0F); 50.0 to 150.0F/C

**Temperature Sensor:** Remote K-Thermocouple Probe with Replaceable Sensor

Unit Weight: 9 lbs

Units/Pkg: 1

Warranty: 12-Month Limited



## **Calibrations**

N100: 1-Point NIST Traceable Calibration N300: 3-Point NIST Traceable Calibration

N400: 3-Point Ultima NIST A2LA Accredited Calibration

#### **Accessories**



A868 - Sensor Dust Filter Sensor Dust Filter - prolong the life of your sensor.



**R400 - Replaceable Sensor** Single K-TC Replaceable Temperature Sensor



**A062 - AC Adapter Extension Cable 10'** 10' Power Extension for R157 AC Adapter



**R066 - Universal Plug Kit for Data Loggers** International Plug Kit for Data Loggers



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

### **Accessories**



**R180 - Replacement AC Adapter** AC Adapter for TSB/TWE/TWP Loggers and the KT8/KT6 series.



**R013 - Temperature Probe** Replacement Bead Wire Temperature Probe



**A203 - Temperature Probe** 6" (15cm) High Temperature Immersion Probe



**A340 - Glycol Bottle**Bottle of Glycol Solution w/ Septum Close



**D605 - Piercing Probe** 4" (10cm) Thermocouple Handled Piercing Probe



### **Accessories**



**D611 - Shielded Immersion Probe** 15' (4.5m) Shielded Thermocouple with 4" (10cm) stainless steel tip



**D617 - Probe Extension** K-Thermocouple 10' (3m) Extension Cable



**A202 - Thermocouple Extension** K-Thermocouple 100' (30m) Extension Cable