

# RHT415 Hygro-Thermometer with Remote Probe


*Simultaneously displays Air Temperature and Humidity with Comfort Level*

## Features:

- Dual LCD display and bargraph
- Color-coded bargraph indicates Dry/Comfortable/Wet conditions
- °F/°C switchable
- Low battery indicator
- Desktop or wall-mount use
- Optional model complete with Certificate of Traceability to N.I.S.T.
- Includes built-in stand, remote sensor with 5ft (1.5m) cable and (2) AA batteries
- 1-year warranty

## Applications:

Hospitals, offices, building inspection, water restoration, greenhouses, warehouses, museums, libraries, offices, storage areas



**NIST**  
TRACEABLE  
CALIBRATION  
AVAILABLE

## Specifications

Air Temperature	14 to 140°F (-10 to 60°C)
Accuracy	±1.8°F/1°C
Relative Humidity	0 to 99%RH
Accuracy	±4%RH
Comfort Level Bargraph	Dry (Red) <40%RH
	Comfortable (Green) 40 to 70%RH
	Wet (Blue) >70%RH
Power	2 AA Batteries
Dimensions	4.4 x 4 x 0.9" (112 x 102 x 23mm)
Weight	8oz (227g)

## Ordering Information:

RHT415 Hygro-Thermometer with Remote Probe  
RHT415-NIST RHT415 with certificate of NIST traceability

 **RoHS**  **CE**