


FLUKE®

15B/17B/18B Digital Multimeters Quick Reference Guide


⚠ See Users Manual for "Safety Information" and complete operating information.

Fuse Test

0.0 - 0.1 Ω = OK 0.099 - 1.01 k Ω = OK




Voltage $\tilde{V}$ $\bar{V}$ mV




PN 3767917 April 2010
©2010 Fluke Corporation. All rights reserved. Printed in China.


Resistance Ω




Continuity $\ni$




LED Test (18B Only)




Current $\tilde{A}$, mA, μA




Capacitance μF




Temperature (17B Only)




Diode Test $\rightarrow$




Duty Cycle % (17B Only)




Frequency (Hz) (17B Only)



Relative Δ (Zero) (17B Only)



HOLD



ToolPak/MH10 (Optional)

