

TCDCS DROP CABLE STRIPPER INSTRUCTIONS



Step 1. Pull plunger to open tool body.




Step 2. Insert the fiber optic cable.



Step 3. Close the tool making sure the plunger is in the locked position.



Step 4. Pull the cables and tool in the opposite directions to strip the cable.



TCDCS SPECIFICATIONS

Slits Drop Cable: 7.9mm to 8.3mm

Length: 3.26" (82.8mm)

Weight: 0.15lb (68g)

Material Body: ABS

Blade: SK5

REPLACEMENT BLADE SETS
TCDCS-2