




ToolSmart™ App Instruction Guide Flashlight Inspection Camera




Flashlight Inspection Camera Pairing




1 Long press the blue Wi-Fi button to activate the FIC's Wi-Fi. Wait for the blue light to come on after the green light comes on.




Go to Wi-Fi settings in the phone. Connect to "IP BoreScope".




3 Tap Toolbox button



4 Tap FIC button




5 Tap Connect



6 Wait for phone and FIC to pair




Flashlight Inspection Camera




1

Hit the capture button to take snapshots and record video. To change between picture and video tap the picture/video button to the right of the capture button.




2

Tap the Gallery



3

Tap image (top) or video (bottom) to view. Hit the Camera button at the bottom to bring up the live view.



4


View image

5

Play video


GENERAL®

» Universal App Settings




1

Click the Hamburger Menu (triple bar button) at the top left corner of the page.



2

Tap the settings button



3

From here, you can change the units of measurement (which applies to all tools), have the captured images save to the phone's gallery, and view the terms & conditions and privacy policy.

GENERAL®

