

Part No.

XTHA-2MS0

1/4" male NPT x male Quick-test XT Adapter, S.S.

Connect to pressure calibrators, gauges or pressure transmitters to 10,000 psi



XTHA-2MS0

Specs/Attributes

Country of origin	USA
Has Check Valve	No
Materials	Stainless Steel
Max Operating Temperature	225 °F / 105 °C
Max Pressure	10000 PSI / 700 bar / 70 MPa
Min Operating Temperature	0 °F / -18 °C
Seal Materials	Teflon, Viton
Wrench Size	5/8 In 16 mm
Connector End 1	1/4" Male NPT (ASME B1.20.1)
Connector End 2	Male Quick-test XT
Dimensions	H: 1.29 in (3.28 cm) x W: 0.63 in (1.6 cm)